

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO.	
2. NAME OF OPERATOR Tesoro Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR 1776 Lincoln St., Suite 1012, Denver, Colorado 80203		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL 1650' FWL		8. FARM OR LEASE NAME Boulder	
14. PERMIT NO.		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7214 GL; 7224 KB		10. FIELD AND POOL, OR WILDCAT Boulder Mancos	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T28N, R1W	
		12. COUNTY OR PARISH Rio Arriba	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input checked="" type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well S.I. unable to produce oil at an economic rate. Tesoro plans to work over and clean out the well according to the following procedure:

1. Pull rods, down hole pump & tubing.
2. Clean out inside of 4½" slotted liner to 3975'.
3. Release & pull the 4½" slotted liner.
4. Clean out the open hole interval from 3041 to 3975' w/a sand pump & chisel bottom bailer.
5. Rerun tubing, down hole pump, rods and test for a few days.
6. If well tests commercial oil production, pull tubing, rods, down hole pump and re-run 4½" slotted liner.
7. Re-run tubing, down hole pump, and rods; place well on production.



18. I hereby certify that the foregoing is true and correct.
SIGNED L. C. Vazquez TITLE District Engineer DATE 4/29/74

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: