UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wel	95 118 22 AM 8: 35
	5. Lease Number
	NM-013657
Type of Well GAS	6. If Indian, All. or Tribe Name
	7. Unit Agreement Name
. Name of Operator	
MERIDIAN OIL	San Juan 28-6 Unit 8. Well Name & Number
. Address & Phone No. of Operator	San Juan 28-6 U 114
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9. API Well No . 30-039-07335
. Location of Well, Footage, Sec., T, R, M	_ 10. Field and Pool
990'FNL, 990'FEL Sec.25, T-28-N, R-6-W, NMPM	Basin Dakota
900	11. County and State
	Rio Arriba Co, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	
Type of Submission Type of Ac	
x Notice of Intent Abandonment	Change of Plans
Subsequent Report Recompletion Plugging Back	New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing Water Shut off
Casing Repair	Water Shut off
	Conversion to Injection
x Other -	
3. Describe Proposed or Completed Operations	<u> </u>
It is intended to workover this Dakota well to repair a suspected csg failure acro existing Dakota perforations with water. The 2 3/8" tbg will be prosqueezed w/cmt below a cmt ret. The casing failure will then be to circ cmt to surface out the bradenhead valve. Cmt will be dried to circ cmt be perforated 7892-7904' w/4 spf and fract tbg will be rerun in the well and the well returned to production.	ulled and the existing perforations squeezed w/cmt and an attempt made dout and the well cleaned out to COTD
igned (KS) Title Regulatory Aff This space for Federal or State Office use) APPROVED BY Title	
CONDITION OF APPROVAL, if any:	A P PMO VED
	2 MAP 2 2 1994
	THE THIRT NIKNIAGED