Form 3160-5 -(June 1590)

	M APPR			
Budget Bur	eau No	<u>/</u> 100	04-013	5
Expires:	March	31,	1993	

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	
	6.

j.	Lease	Design	ation	and	Serial	No.	

SUNDRY NOTICE	ES AND REPORTS ON WILLES	/ SF-079290
Do not use this form for proposals	to drill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION	FOR PERMIT - " for such proposals	
		7. If Unit or CA, Agreement Designation
		SAN JUAN 28-7
1. Type of Well Oil Well Other		8. Well Name and No.
	Attention:	SAN JUAN 28-7 UT #26
2. Name of Operator AMOCO PRODUCTION COMPANY		9. API Well No.
3. Address and Telephone No.		3003907351
P.O. Box 800, Denver, Colorado 802	201 (303) 830-4912	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey		BLANCO MESAVERDE
		11. County or Parish, State
990 FSL 910FWL	Sec. 24 T 28N R 7W UNIT M	RIO ARRIBA NM
12. CHECK APPROPRIATE	BOX(s) TO INDICATE NATURE OF NOTICE	CE , REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF AC	TION
	<u> </u>	F1
	Abandonment	Change of Plans New Construction
Notice of Intent	Recompletion Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing Other BRADENHEAD REPAIR	Conversion to Injection
Final Abandonment Notice		Dispose Water Lote: Report results of multiple completion on Well Completion or
	state all pertinent details, and give pertinent dates, including estimated date	ecompletion Report and Log form.)
	PECE Feb 1 OIL COL	5 1995 U
14. I hereby certify that the foregoing is true and correct Signed	Title BUSINE	SS ANALYST Date 01-03-1995
(This space for Foderal or State office use)		ACCEPTED FOR SECOND
• • • • • • • • • • • • • • • • • • • •		•
Approved by	Title	FEB 10 1995
Conditions of approval, if any:		
Title 18 U.S.C. Section 1001, makes it a crime for any representations as to any matter within its jurisdiction.	person knowingly and willfully to make to any department or agency of the l	Inited States any ARMINISTID HISTORIES
	• See Instructions on Reverse Side	

SAN JUAN 28-7 #26 REPAIR

121594 MIRUSU, CSG PRESS 320#, TBG 300# INTERMEDIATE 10# BRADENHEAD 0#, PULL

TBG, SET RBP AT 4000' IN THE 5 1/2" AND TESTED TO 1000#.

DUMPED 1 SX SAND ON RBP

PULLED 2964' OF 5.5" CSG

TIH W/7" SCRAPER, CIRC HOLE CLEAN, TOH.

RAN GR, CBL AND CLL FROM 100 TO 2950 IN THE 7" CSG. APPEARED TO HAVE CMT BOND

IN FORMATION BUT NOT TO PIPE.

SET RBP AT 2902, PULL ONE JOINT TBG, SET PKR AND TESTED TO 1000#,

SHOT SOZ HOLES AT 2860-2861 W/ 2 JSPF

PKR SET AT 2646 AND RBP AT 2917

SQZED FROM 2664 TO 2917 W/ 100SX CL B CMT AT MAX PSI OF 1100 AND MAX RATE OF 2.2

BPM. RETRIEVED PKR

RAN GR, CBL AND CLL FROM 2350 TO 2770

SHOT SQZ HOLE AT 1900-1901 W/ 2 JSPF

SET PKR AT 1705 SQZED FROM 1705 TO 1900 W/ 100SX CL B AT MAX PSI OF 1400 AND MAX

RATE OF 2.0 BPM, LET SET FOR 4 HRS, RELEASED PKR

SHOT SQZ HOLES AT 200-201 W/ 2 JSPF

SQZED FROM 200 TO SURF W/ 146 SX CL B AT MAX PSI OF 80 AND MAX RATE OF 2 BPM

8 BBLS OF CMT TO SURF

DRILLOUT CMT FROM 0-200. 1705- 1900 AND 2845 - 2917.

CIRC SAND TO RBP AT 2917

PULLED RBP FROM 2917

CIRC

RAN 5 1/2" CSG BACK IN AND TIED CASING BACK AT 2694.

SET SLIPS

CIRC

PULLED RBP FROM 4000'

CIRC

SET 2 3/8" PRODUCTION TBG AT 5521'

SHUT WELL IN

RDMOSU 122794

DOCUMENT 28726