(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4. Approval expires 12-31-60. New Mexico

nd	Office			_	_	_	_	_	_	~	_	_	_	_	_	
	1	0	ć	į	Ć	Ì	C	į	١	ķ						

Lease No. San Juan 28-6 Unit Unit 14-06-001-1051

CLINDRY NOTICES AND DEPORTS ON WITH

NOTICE OF INTENTION TO DRILL	
The state of the british state of the state	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHI	UT-OFF SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR RE	PAIR WELL SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACID	IZESUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER	The state of the s
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABO	OVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	June 7 19 5
Well No. is located	IG 2001 Good 2007
SW Section 23	28 1 6 4 N.H.P.H.
(1/2 See and Sec. No.)	(Twp.) (Range) (Meridian) Rio Arriba (Meridian)
(Field)	(County or Subdivision) (State or Territory)
State names of and expected depths to object	
On 6-4-57. Total Dept Ran 101 joints 7-5/8' with 100 sacks regula followed with 50 sack Held 1000# 30 minutes	', J-55, 26.40f, Casing (3438') set at 3500' ar communt,100 sacks Pozmix, 50f Plocele and 4% Gel,
On 6-4-57. Total Depi Ran 101 joints 7-5/8' with 100 sacks regula followed with 50 sack Held 1000\$\frac{2}{2} 30 minutes Top of coment by temps I understand that this plan of work must related the same of the	th 3501'. J-55, 26.40f, Casing (3438') set at 3500' ar cement, 100 sacks Pozzix, 50 Plocele and 46 Gel, is liest cement. Frature survey at 2500'. CON. COM. COM. COM. COM. COM. COM. COM. COM
On 6-4-57. Total Dept Ran 101 joints 7-5/8' with 100 sacks regula followed with 50 sack Held 1000\$\frac{2}{2}\$ minutes Top of cament by temps I understand that this plan of work must related to the first limits of the first limits and the first limits are seen to the first limits and the first limits limits limits and the first limits l	th 3501'. J-55, 26.40f, Casing (3438') set at 3500' ar cement, 100 sacks Pozzix, 50 Plocele and 46 Gel, is liest cement. Frature survey at 2500'. CON. COM. COM. COM. COM. COM. COM. COM. COM

