UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



BUREAU OF LAND MANAGEMENT		
Sundry Notices and Reports on Wel	ls	St JAN 19 AM 8: 15
1. Type of Well GAS	5. 6.	Lease Number NW SF-079519A If Indian, All. or Tribe Name
2. Name of Operator MERIDIAN OIL	7. 8.	Unit Agreement Name San Juan 28-5 Unit Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		San Juan 28-5 U 48 API Well No.
4. Location of Well, Footage, Sec., T, R, M 1150'FSL, 850'FWL Sec.22, T-28-N, R-5-W, NMPM		Field and Pool Blanco Mesa Verde County and State Rio Arriba Co, NM
Subsequent Report Plugging Back Casing Repair	:ion _ Ch _ Ne _ No: _ Wa	PORT, OTHER DATA ange of Plans W Construction n-Routine Fracturing ter Shut off nversion to Injectio
It is intended to perforate and fracture stimulate the the following intervals of the were bypassed during original completion and are all located below The tubing will be pulled from the well. A bridge plug will be set Selected intervals from 5542-5716' will be perforated and fracture packer. A bridge plug will be set \$\infty\$ 5510'. Selected intervals from fracture stimulated. The bridge plugs will be retrieved from the way well, and the will returned to production.	w the 5740 e stimum 5420 ell, the	Huerfanito Bentonite @ 4751'. D' above the Point Lookout. Ulated through tubing and a S-5486' will be perforated and
JAN2 6 19 OIL CON."	94 DIV	3
Signed Title Regulatory Afr	****	Date 1/14/94
(This space for Federal or State Office use) APPROVED BYTitle CONDITION OF APPROVAL, if any:	6	1994 1STRICT MANAGER