submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	_
RECEIVED	
DLIT	
	RECEIVED BLM

BUREAU OF LAND MANAGEMENT	2001
Cundry Notices and Benerts on Wel	94 JAN 19 AM 8: 14
Sundry Notices and Reports on Wel	
1. Type of Well GAS	5. Lease Number SF-079520 6. If Indian, All. or Tribe Name
	7. Unit Agreement Name
2. Name of Operator MERIDIAN OIL	San Juan 28-5 Unit 8. Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	San Juan 28-5 U 37 9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1650'FSL, 800'FWL Sec.24, T-28-N, R-5-W, NMPM	10. Field and Pool Blanco Mesa Verde 11. County and State Rio Arriba Co, NM
Subsequent Report — Recompletion — Plugging Back — Casing Repair —	
13. Describe Proposed or Completed Operations It is intended to perforate and fracture stimulate the the following intervals of the were bypassed during original completion and are all located below The tubing will be pulled from the well. A bridge plug will be set Selected intervals from 6114-6366' will be perforated and fracture packer. A bridge plug will be set @ 5500'. Selected intervals from fracture stimulated. The bridge plugs will be retrieved from the well, and the will returned to production.	low the Huerfanito Bentonite @ 4871'. @ 6736' above the Point Lookout. ire stimulated through tubing and a om 5005-5405' will be perforated and well, the tubing will be run back in the
well, and the will returned to production. REGEI JAN2 4199 OIL CON. I	4 🖳
14. I hereby certify that the foregoing is true and of Signed Market Title Regulatory As	
(This space for Federal or State Office use)	APPROVED
APPROVED BYTitle CONDITION OF APPROVAL, if any:	Date 1100 2 0 1994