

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		5. LEASE DESIGNATION AND SERIAL NO. SF-079519A
1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR El Paso Natural Gas Company		7. UNIT AGREEMENT NAME San Juan 28-5 Unit
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499		8. FARM OR LEASE NAME San Juan 28-5 Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990'N, 1650'E		9. WELL NO. 8
10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde		11. SEC. T., R., M., OR BLM. AND SURVEY OR AREA Sec. 21, T-28-N, R-5 -W N.M.P.M.
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, ST, GR, etc.) 6646'GL	12. COUNTY OR PARISH 13. STATE Rio Arriba NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PELL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to plug back the Mesa Verde and recomplete the Fruitland Coal formation in this well in the following manner:

Set cmt retainer @ 5250'. Run caliper and CBL. Squeeze Mesa Verde perms with 243 sx (287 cu.ft.) cmt. Spot 15 sx (18 cu.ft.) cmt on top of retainer. Perf 4 squeeze holes 10' above cement top of CBL. Set cmt retainer 10' above squeeze holes. Squeeze with sufficient cmt to bring cmt top to 2800'. Drill out cmt. retainer. Pressure test to 2000 psi. Run CBL, GST, NGT logs. Spot 700 gal 7 1/2% HCl across perforations. Perforate w/2 spf at 3398-3428', 3516-3531'. Fracture stimulate with 130,000# sand and 102,175 gal. fluid. Flow well back. Land tbq near 3530'.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Regulatory Affairs (CS) 09-12-89

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE AREA MANAGER

CONDITIONS OF APPROVAL IF ANY: