Form 3180-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Bu

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

CHAIDDY MOTICES	AND REPORTS ON WELLS	5. Lease Designation and Serial No.
	ill or to deepen or reentry to a different reservoir.	SF-079289-A
	DR PERMIT - " for such proposals	6. If Indian, Allottes or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well		SAN JUAN UT
Oth West Other		8. Well Name and No.
2. Name of Operator AMOCO PRODUCTION COMPANY	Attention:	SAN JUAN UT #9
3. Address and Telephone No.	WAYNE BRANAM, RM 1948	3003907399
P.O. Box 800, Denver, Colorado 80201	(303) 830-4912	10. Field and Pool, or Exploratory Area
4. Location of Well (Feotage, Sec., T., R., M., or Survey Descrip	ption)	BLANCO MESAVERDE
000 501 4000514	0 44 T 00N P 7W NEWTAA	11. County or Parish, State
890 FSL 1090FWL	Sec. 14 T 28N R 7W UNIT M	RIO ARRIBA NM
OUTOW ADDODDIATE DO	VALUE OF MOTOR OF	
	X(s) TO INDICATE NATURE OF NOTICE, F	SEPURI, UR UTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
	Abendonment	l a
Notice of Intent	Recompletion	Change of Plans New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Ceeing Other CMT WORK	Conversion to Injection Dispose Water
	(Note: Rep	ort results of multiple completion on Well Completion or on Report and Log form.)
		OIL GOLL, DIV.
	•	Divis. 3
14. I hereby certify the pure foregoing justice and correct Signed	Title BUSINESS AN	ALYST Date 03-15-1995
(This space for Federal or State office use)		
•	1.00	CEDTED FOR DECOSES
Approved by	Title	CEPTED FOR RECORD
Conditions of approval, if any:		
Tue 18 11 0 0 Sealer 1001	pouringly and willfully be make to any department an analysis at 11-1-14 days	MAR 2 2 1995
Title 18 U.S.C. Section 1001, makes it a crime for any person kn representations as to any matter within its jurisdiction.	nowingly and willfully to make to any department or agency of the United State	
	1111000	ARMINGTON DISTRICT OFFICE

SAN JUAN 28-7 #9 BRADENHEAD REPAIR

MIRUSU 122194

TOH W/TBG

RAN SCRAPER TO 4920

SET RBP AT 4841, PUMPED 85 BBLS OF WTR/CLAY FIX TO TEST RBP, LEAKED

RESET RBP AT 4740 AND STILL LEAKED

TOH W/RBP

RAN CBL AND GR

TOH W/ 4.5" CSG

RAN CBL.

SET RBP AT 3180, TESTED CSG TO 1000# AND HELD

PERF AT 2960-61 W/2 JSPF TOTAL OF 2 SHOTS

SQZ FROM 2960 TO 2510 W/ 164 SX CLASS B AT MASX PSI 1600 AND MAX RATE 2.5 BPM

PLUGBACK 2803 TO 2960 W/ 36 SX STD CMT W/ 3% HALAD 344 AND 5% CAL SEAL (6 BBLS)

SET PKR AT 2680

PERF 2320-21 W/ 2 JSPF TOT OF 2 SHOTS

SET PKR AT 2010

SQZ FROM 2320 TO 1711 W/ 173 SX CL B AT MAX PSI 1500# AND MAX RATE 2 BPM

PLUGBACK 2320 TO 2202 W/ 27 SX OF CL B WITH 3% HALAD 344 AND 5% CAL SEAL

PERF 180-81 W/ 1 JSPF TOT 2 SHOTS\

SQZ 8 TO 180 W/ 27 SX CL B AT MAX PSI OF 200 AND MAX RATE OF 2 BPM

PLUGBACK 0 - 180 W/ 38 SX CL B WITH 3% HALAD AND 5% CAL SEAL

DO TO 196

PRS TEST TO 500# LEAKED DOWN TO 100#

DO TO 2992

SET PKR AT 248

TESTEDCSG TO 300# HELD

CLEAN OUT SAND

TOH W/RBP

RUN 4.5" CSG TO 3187

PRESS TESTED CSG TO 1000# IN 4 1/2"

CLEANED OUT TO THE TOP OF THE RBP AT 4830'

LANDED 2.375" TBG AT 5790

WELL RETURNED TO PRODUCTION

DOCUMENT 28709