Form 3160-5 November 1983) Formerly 9-331) DEPARTMENT OF THE IN BUREAU OF LAND MANAGI		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. Lease designation and serial no. SF-079289 6. NY INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORT (Do not use this form for proposals to drill or to deepen of Use "APPLICATION FOR PERMIT—" for	RTS ON WELLS or plug back to a different reservoir. FECEIVED	7. UNIT AGREEMENT NAME
OIL WELL OTHER 2. Name of OFERATOR Tennech 011 Company	FEB 21 1986	San Juan Unit 28-7 8. FARM OR LEASE MAKE
P.O. Box 3249, Englewood, CO 80155	BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA	23
4. LOCATION OF WELL (Report location clearly and in accordance we See also space 17 below.) At surface 990' FNL, 990' FEL	rith any State requirements.*	10. PIRLO AND POOL, OR WILDCAT Blanco Mesaverde 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 15, T28N, R7W
14. PERNIT NO. 15. BLEVATIONS (Show will see that the second see that the second secon		12. COURTY OR PARISH 13. STATE Rio Arriba NM
16. Check Appropriate Box To Indi	icate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	Paraeus.	PENT EEFORT OF:
FRACTURE TREAT SHOOT OR ACIDIZE BEPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHAMGE PLANS	WATER SEUT-OFF PRACTURE TREATMENT SECOTING OR ACIDIEING (Other) Progress	
(Other)		of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurfment to this work.)	pertinent details, and give pertinent dates, ace locations and measured and true vertice	including estimated date of starting any al depths for all markers and sones perti-
1/30/86 MIRURT. Blow well dn, pump tbg head. Broke off stud to donut. Drilled out stud. Weld patch on tbg tbg. Work pipe and wait on Petro lo 4760'. POOH, LD 152-1/2 jts or 2-3	NUBOP. Weld on stud. Br spool. Pull donut w/6500 a. Free point tbg @ 4748'	roke twice more. 10#. Unable to pull Jet cut tbg @
1/31/86 PU 2-7/8" DP, TIH. Clean oretainer on WL @ 4347'. TIH, Est in hole. Test 7" csg and DP to 1000 ps - 35 POZ w/6% gel and 150 sx (180 cf reverse out 1 bbl cmt. TOOH. NDBOP	jection rate @ 2.5 BPM and i. OK. Squeeze open hole) "B" w/2% CaCl ₂ . Squeeze	1 1000 psi. Load e w/250 sx (375 cf) 65
2/1/86 NU spool and BOP. PT to 100 Shear mill and cut 2' w/starting mil	O psi, OK. PU whipstock a l. POOH. PU speed mill,	and RIH. Set @ <u>4329'</u> .
2/2/86 Mill window to 4336'. Work PU speed mill #2 and TIH. Ream wind back off at 4302'. Fish consists of TOOH. PU screw in sub, bumper sub, Jar loose and TOOH.	low from 4331' to 4332'. ! speed mill, bit sub, x-o	Mill stuck. RU Homco, ver and 1 jt DP.
18. I bereby earlify that the foregoing is true and correct 813NED WW Olluw TITI	Administrative Cole Kt	2-18-86
(This space for Federal or State office use)	MAR 1 0 1986	ACCEPTED FOR RECORD
APPROVED BY	OIL CON. DIV.	MAR () 6 1986
	MOCC DIST. 3	FARMINGTON RESOURCE AREA

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any faise, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

1

ŧ

2/3/86; POOH, LD fishing tools. PU tapered mill and TIH w/2 DC's. Clean out window, circ. TOOH, PU speed mill and RIH. Ream 3' to bottom, mill to 4341'.

2/4/86 TOOH w/speed mill #2. TIH, Ream to btm, switch to air/foam/mist. Unable to make hole, TOOH. Mill wore out. PU mill #3, TIH. Mill at 4341'. Not making new hole, TOOH. Mills wore out and indicate cutting csg, not whipstock.

2/5/86 POOH, PU mill and TIH to 4337.5'. Mill 6", POOH. TIH w/muleshoed tbg and C/O to 4338.5'. POOH, PU speed mill #5, TIH and begin milling @ 4337.5'.

2/6/86 Milling w/speed mill #5, TOH, PU mill, TIH. Mill to 4338.5'

2/7/85 TOH w/mill #5. TIH w/mill #6. Made l' hole. POOH. Set retainer @ 4261'. TIH w/whipstock #2 set @ 4261', top whipstock @ 4243'.

2/8/86 Mill w/starting mill to 4246', circ. TOH. PU speed mill #1 and TIH. Mill to 4250', PU speed mill #2, TIH, ream 5' to bottom. Mill to 4252', change to air mist.

2/9/86 Blow and unload hole, mill to 4254'. POOH (speed mill #2 polished). TIH w/speed mill #3. Mill to 4256'. Recovering shale from 4254=1/2'. Circ, POOH, PU re-run mill and DC, TIH. Repair starter on #1 motor. FTIH. Ream window from 4243 - 4256'. Circ, survey, strap out of hole.

2/10/86 S.L.M. PU bit #1. RIH to 4243', blow hole, RIH to 4256', drill and survey to 4556'.

2/12/86 Drill to TD of 5497', blow hole, POOH, RU Welex and log.

2/13/86 Finish logging. Ran DIL and SDL. Log from 5500 to 4243'. TOH, lay down tools, TIH w/DP and collars. Blow hole. LDDP and DC's. Run 133 jts 4-1/2" 10.5#, K-55 ST&C. Total 5507', landed 0 5500', FC 0 5448, FJ 0 4410. Blow hole. Cmt w/200 sx Class B + 6% D-60 and (240 cf) 20 bbl CW 100. PD 0 6:45 PM 2/14/86. ND. Set 80,000# on slips. Release rig 0 10:00 PM on 2/13/86. Disp w/1% KCl.

18. I hereby sentify that the foregoing is true and correct SIGNED WWW.	TITLE _	Administ Dia Becations	2-18-86
(This space for Federal or State office use) APPROVED BY	TITLE_	MAR 1 01986	
CONDITIONS OF APPROVAL, IF ANT:		OIL CON. DIV.	
•\$•	e Instruct	ions on Reverse Side	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.