

## J. M. HUBER CORPORATION DAILY WELL REPORT

District DenverDeal No. 31-M-222-BWell #16-1 Jicarilla-Apache County Rio ArribaState New MexicoLocation SE 1/4 Section 16-28N-2W (1820' FWL, 1670' FWL)Operator Huber Contractor Huber WI3/8Remarks 8500-foot Morrison test. (WC)

Date	Depth	Report
5-6-74		16 hrs SITP 550#, SICP 1900#. Blew condensate to pit, water followed. Turned thru production unit. WTP 250#, WCP 600#. Gas volume 320 mcf. Gas volume fell to 47 mcf in 10 mins due to more frac fluid coming into well bore. Will continue cleaning up well.
5-7-74		SICP, SITP 400#, SICP 1450#. Opened tbq. No fluid to surface. Will leave shut-in a few hours. Waiting on swabbing unit.
5-8-74		SITP 700#, SICP 1900#, flowed frac fluid 1 hr, 20 mins thru tbq. Recd 40 bbls, CP fell to 375#. SI. Waiting on swab unit to clean up well.
5-16-74		7 days SITP 2550#, SICP 2500#. Flowed frac fluid 5 1/2 hrs until well died. CP blew down to 340#. Recovered condensate and water. Chloride content of water is 6,988 milligrams per liter.
5-17-74		SITP 825#, SICP 1550#. Flowed frac fluid 3 hrs., well died.