
Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR



	BUREAU OF LAND MANAGEMENT	5. LEASE DESIGNATION AND SERIAL NO.
	RECEIVED	SF-078498A
	SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Do not use this form for proposals to drill or to deepen or reentry 🗗 addifferen reservoir.	nal
	Use "APPLICATION FOR PERMIT-" for such proposals	US
	SUBMIT IN TRIPLICATE 070 FARMINGTON, N	7. IF UNIT OR CA, AGREEMENT DESIGNATION
-	TYPE OF WELL	
٠		8. WELL NAME AND NO.
2	OIL WELL GAS WELL OTHER:	San Juan 28-7 Unit #252
	CONOCO INC.	9. API WELL NO.
3.	ADDRESS AND TELEPHONE NO.	30-039-21653 10. FIELD AND POOL, OR EXPLORATORY AREA
	10 Desta Drive, Ste. 100W Midland, Texas 79705-4500 (915-686-5424)	BLANCO MV/DAKOTA
4.	LOCATION OF WELL (Footage, Sec., T., R., M., or Survey Description)	11. COUNTY OR PARISH, STATE
	790' FNL - 1850' FWL: SEC. 32 T28N=R07W UNIT LETTER 'C'	RIO ARRIBA, NM
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	
TYPE OF SUBMISSION TYPE OF ACTION		
	DECISION SIN	2 01 7011014
	Notice of Interest E G G G G G G Abandonment	Change of Plans
	Subsequent ReporAU6 2 2 1997	New Construction
	Final Abandonment Notice Casing Repair	Non-Routine Fracturing
	Final Abandonment Notice OCasing Repair Altering Casing	Water Shut-Off
	DIST. 3 Other: Change tubing & test	Conversion to Injection
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propositionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		estimated date of starting any proposed week. Missell is
	NU BOP. Unset tbg hanger, rubber seal rings cut. TIH & tag PBTD @ 7024' 31'	of fill TOOH w/ 230-its 2-2/3" 4.7# L55 tha. 8
	1.78" ID SN, pulled last 16-stands wet. Found plunger spring stop scaled in SN, 1	It of the holes Chi had and the Did.
	well and secure for night	-31 of the below SN had scale build-up on ID. SI
	well and secure for night.	
	well and secure for night. 8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be	een above the SN would not drift. CO fill from
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night.	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes. Fl
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/ tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes. Fl
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO.	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes. Fl
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/ tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO.	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/ tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/ tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE SIGNED (This space for Federal or State office use)	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE SIGNED TITLE As Agent for Conoco in TITLE APPROVED BY TITLE	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
14.	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/1 tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE SIGNED TITLE As Agent for Conoco In (This space for Federal or State office use)	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.
	8/04/97 SICP=180#, bled well to tank. TIH w/ bailer, drifting 2-3/8" tbg, the joint hat had be 7024' to PBTD @ 7055'. TOOH w/ bailer and tbg, recovered frac sand. TIH w/ 1/tbg to 6901' (SD 30-Mins for Lightning). Install tbg hanger. ND BOP. Install WH. tag FL @ 6000', swabbed dry in 2-runs. SD for 1-hr, RIH w/ swab and tag FL @ 6 fluid in 3-hrs. SI well and secured for night. 8/05/97 SICP = SITP = 170#. Bled off tbg. RU swab. FL @ 6000'. Made 2-swab runs to @ 6000' ea. run, Pcsg held at 160#. Rec 25-Bbls in 12-Hrs. SI well & secured for 8/06/97 SITP = SICP = 170#. RD swab. RDMO. I hereby certify that the foregoing is true and correct DEBRA BEMENDERFE SIGNED TITLE As Agent for Conoco in TITLE APPROVED BY TITLE	een above the SN would not drift. CO fill from 78" ID SN on 226-Jts of 2-3/8" 4.7# J-55 8rd EUE RU to swab. Tag FL @ 6000', made 3-swab and 6000', swabbed dry in 2-runs. Made 12.5-Bbls of SN, tbg dry. Making 1-run every 45-minutes, FL r night.

* See Instruction on Reverse Side

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

AUG 2 0 1997