Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. LEASE DESIGNATION AND SERIAL NO.

					31	078300A	
	SUNDRY NOTICES AND REPORTS ON WELLS					DIAN, ALLOTTEE OR TRIBE NAME	
	Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.						
	Use "APPLICATION FOR PERMIT-" for such proposals 10 20 20						
		SUBMIT IN TRIPI	ICATE	(6)110	N + 1	IT OR CA, AGREEMENT DESIGNATION	
1.	TYPE OF W	/FI )		AII		N JUAN 28-7 DK NAME AND NO.	
٠.	OIL WELL			, 1900 Sou	》。WELL 第19		
2.	NAME OF (			<u> </u>	<u>~</u>	ELL NO.	
	CONOC				58	039-21734	
3.		AND TELEPHONE NO.	- E		<del></del>	AND POOL, OR EXP_ORATORY AREA	
	P.O. Box	P.O. Box 2197, DU 3066, Houston, TX 77252-2197 (281) 293-1613				SIN DAKOTA	
4.		OCATION OF WELL (Footage, Sec., T., R., M., or Survey Description)			11. COUN	ITY OR PARISH, STATE	
	2120' FSL & 800' FWL, Section 19, T28N, R07W, Unit Letter L					ARRIBA COUNTY	
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTIGE, REPORT, OR OTHER DATA						
	TYPE OF SUBMISSION TYPE OF A				E OF ACTION	1	
		Notice of Intent	☐ Abana	lonment		Change of Blazz	
					<u> </u>	Change of Plans	
	$\boxtimes$	Subsequent Report		npletion	<u> </u>	New Construction	
		Final Abandonment Notice		ng Back	<u> </u>	Non-Routine Fracturing	
				g Repair	<u> </u>	Water Shut-Off	
				g Casing	L	Conversion to Injection	
			Other:	Tubing Upgrade	(Note	Dispose Water  Report results of multiple completion on Well Completion or	
13.	Recompletion Report and Log Form )						
	directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)						
	8/2/00 415 psi casing. 415 psi tubing. Safety meeting. MIRU. Blow well dow			n, no water needed to kill. ND			
	wellhead, NU BOP. PU ISTD. 1-1/2" tubing. To tag for fill. Tall fill). Secure well for night.			To tag for fill. Tally OOH, laying down. Tagged fill at 7358'.			
					0.0/01 1.55 51.5		
8/3/00 0 psi on tubing and casing. Safety meeting. RIH with 226 joints 2-3/8", J-55 EUE tubing and land a with a mule shoe and seating nipple on bottom. Rig up to swab. Tagged fluid at 6200', make 5 swand retrieve 26 bbls fluid. Secure well for night.					ubing and land at 7168'		
					oo, make 5 swab fulls		
	8/4/00 150 tubing, 150 casing. Safety meeting. Blow well down, RIH with swab, tag fluid at 6100'. Make 6 runs						
until casing psi came up to 295 psi. Kicked well off, let fluid blow up tubing. Retrieved 30 bbls fluid.							
	move. Turn well over to sales.						
14. I hereby certify that the foregoing is true and correct							
	SIGNED	Delna attners	TITI F	DEBRA SITTNER, As A	gent for Conor	20 Inc. DATE 8/14/00	
(This space for Federal or State office use)					20 110. DATE 0/14/00		
	APPROVE		TITLE			DATE	
Conditions of approval, if any:							
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the Unites States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	included of fraudulent statements of representations as to any matter within its jurisdiction.						

\* See Instruction on Reverse Side

WG 1 8 2000