

(A1b)

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

JC 83

6. If Indian, Allocated or Tribe Name

Jicarilla Apache
Tribe

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Jer #2

9. API Well No.

30 039 21755

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal /pc

11. County or Parish, State

Rio Arriba County, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325-1821

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1850' FNL & 1700' FEL (Unit G)
Sec. 7, T28N, R3W, NMPM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to plug and abandon this wellbore as follows:

- 1.) Tag CIBP @ 4060'. Spot class B plug inside casing from 4060' to 3850'. Top of Fruitland at 3945'.
- 2.) Set tubing at 3702'. Spot class B plug from 3702' to 3550' to cover Ojo Alamo. Ojo Alamo top @ 3652'.
- 3.) TOH. Perforate casing @ 265'. Fill casing inside and out with class "B" w/4% gel.
- 4.) Set dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed

Title Operations Manager

Date 3/19/97

(This space for Federal or State office use)

Approved by

Title

Chief, Lands and Mineral Resources

Date MAY 12 1997

Conditions of approval, if any:

To the surface as per attached letter

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator Dugan Prod. Co. Well Name Jer #2

1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. For wells on Federal leases, Al Yepa with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Erwin Elote with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-3242.

3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made : None