UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Budget Bureau No. 42-R1424
ES	5. LEASE
INTERIOR	SF 079290-A
RVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	•

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use forms 4-31-10 for such proposals.) 1. oil gas well D other 2. NAME OF OPERATOR 5. Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, New Mexico 874-01 AL LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOPA PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally direct locations and measured and true vertical depths for all markers and zones pertinent to this work.)* (7-18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Cerculated to surface. WCC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328' Cemented w/ 282 cu. ft cement. WCC 12 hours; held 1200#/30 minutes. Top of cement at 1900'. 5-80: TD 5593'. Ran 62 joints 4 1/2", 10.5#, K-55 casing liner 2477' set 3116-55; Float collars et at 5573'. Cemented w/ 426 cu. ft. cement. WCC 18 hours.		_
1. oil gas well D other 2. NAME OF OPERATOR E1 PASO NATURAL GAS COMPANY 3. ADDRESS OF OPERATOR P.O. BOX 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 800'S, 1520'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* (7-18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328'. Cemented w 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.	* * · · · · · · · · · · · · · · · · · ·	Con Tuon 28 7 Unit
San Juan 28-7 Unit	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 800'S, 1520'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES MULTIPLE COMPLETE NOTICE NOTICE NEW MEXAL MARCH NEW ACCOUNTY NEW MEXAL MARCH NEW ACCOUNTY NEW MEXAL MARCH NE	1. oil — gas —	
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHORT OF SUBSEQUENT REPORT OF: 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and consepertment to this work.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and consepertment to this work.) 18. ELEVATIONS (SHOW DF, KDB, AND WD) 19. ELEVATIONS (SHOW DF, KDB, AND WD) 10. ELEVATIONS (SHOW DF, KDB, AND WD) 10. ELEVATIONS (SHOW DF, KDB, AND WD) 11. SEC., T., M., OR BLK, AND SURVEY OR AREA Sec. 24, T-28-N, R-7-W NMPM 12. COUNTY OR PARISH 13. STATE Rio Arriba New MEXICO 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 16. CLECK APPROPRISH 13. STATE Rio Arriba New MEXICO 16. CHECK APPROPRISH 13. STATE Rio Arriba New MEXICO 17. API NO. 18. COUNTY OR PARISH 13. STATE Rio Arriba New MEXICO 19. COUNTY OR PARISH 13. STATE Rio Arriba New MEXICO 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6243' GL 16. CHECK APPROPRISH 13. STATE Rio Arriba New MEXICO 16. CHECK APPROPRISH 13. STATE Rio Arriba New MEXICO 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true ve		
3. ADDRESS OF OPERATOR P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below) AT SURFACE: 800'S, 1520'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* (7-18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3266'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328'. Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.		
P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 800'S, 1520'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL Grant Substitute of the stating any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 10-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328 Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* (-18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328' Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.	P.O. Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 24, T-28-N, R-7-W
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF		, i
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF		
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 18-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328 Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.		_
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* -18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328 Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.	·	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* -18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328 Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'.		6243' GL
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 7-18-80: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 40#, K-55 surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 8-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328' Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'. 8-80: TD 5593'. Ran 62 joints 4 1/2". 10.5#, K-55 casing liner 2477' set 3116-55.	SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	change on Form 9–330.)
surface casing 214' set at 228'. Cemented w/ 224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes. 3-80: TD 3286'. Ran 80 joints 7", 20#, K-55 intermediate casing 3275' set at 328' Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'. 5-80: TD 5593'. Ran 62 joints 4 1/2". 10.5#, K-55 casing liner 2477' set 3116-55!	including estimated date of starting any proposed work. If well is	directionally drilled, give subsurface locations and
Cemented w/ 282 cu. ft cement. WOC 12 hours; held 1200#/30 minutes. Top of cement at 1900'. 5-80. TD 5593'. Ran 62 joints 4 1/2". 10.5#, K-55 casing liner 2477' set 3116-55	surface casing 214' set at 228'. Cement	ted w/ 224 cu. ft. cement.
5-80: TD 5593'. Ran 62 joints 4 1/2", 10.5#, K-55 casing liner 2477' set 3116-55 Float collar set at 5573'. Cemented w/ 426 cu. ft. cement. WOC 18 hours.	Cemented w/ 282 cu. ft cement. WOC 12 hou	ermediate casing 3275' set at 328' rs;held 1200#/30 minutes. Top of
	5-80: TD 5593'. Ran 62 joints 4 1/2", 10.5#, K-	55 casing liner 2477' set 3116-55 6 cu. ft. cement. WOC 18 hours.
	TOWN COTTON DOG GO NAID . COMMENTED IN	

Subsurface Safety Valve: Manu. and Type		Set @	_ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Drilling Clerk	DATE	July 25, 1980	
(This space for Federal or State office use)			_
APPROPER TO FOR RECORD TITLE TITLE	DATE .	<u> </u>	

AUG 05 1980

FARMINGTON DISTRICT

*See Instructions on Reverse Side