For. 3160-5 (August 1999)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO 1004-0135 Expires: November 30, 2000

	13/10/11/03: 140	, .
5.	Lease Serial No. /	_
	NMSF 079290	/

SUNDRY NUTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
-bdddd	

abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.						
1. Type of Well ☐ Oil Well	her		8. Well Name and No. SAN JUAN 28-7 258M				
Name of Operator CONOCO INC.	DEBORAH MARBERRY E-Mail: deborah.a.marberry@conoco.com			9. API Well No. 30-039-25557			
3a. Address P.O. BOX 2197 DU 3066 HOUSTON, TX 77252		3b. Phone No. Ph: 281.293 Fx: 281.293	(include area code 3.1005 .5466)	10. Field and Pool, or Exploratory BLANCO MESAVERDE / BASHY DAKO		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	1)		11. County or Parish, and State			
Sec 23 T28N R7W SWNW 15	523FNL 933FEL /			RIO ARRIBA COUNTY, NM /			
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHEI	R DATA	
TYPE OF SUBMISSION			TYPE OF ACTION				
□ Notice of Intent	☐ Acidize ☐ Deepen			☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Frac	rure Treat 🔲 Reclam		ation	☐ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ New	Construction	☐ Recomp	olete	⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempor	arily Abandon	Workover Operations	
	☐ Convert to Injection	☐ Convert to Injection: ☐ Plug Back ☐ Water D		Disposal			
Conoco performed workover of 4/25/2002 Road rig to location pit. SHUT DOWN. 4/26/2002 Kill tubing. NDWH & OK. POOH with 40 jts of 2 3/8 4/29/2002 Check well pressur tubing with Mule Shoe Collar, FROM PREVIOUS DUMP AC RIH with Mule Shoe Collar, SN DK perf @ 7883'. Pull up and 4/30/2002 Check well pressure RIH with 2 3/8" tubing with Ha	. Spot unit and equipment NUBOP. Set back press "tubing. SHUT DOWN e. Csg - 225 psi. Blow we and SN. NOTE: HAD 2 J ID JOB. RIH with sand lir N and 251 jts of 2 3/8" tub shut down. e. Csg - 210 psi. Blow we llib Tbg. Baler. Tagged sa	nt. Change out sure valve. Te ell down. POOI TS OF TUBIN ne to check for ping. Tagged fi ell down. Kill tu	diesel tank. Rig st BOP'S - H and tally 207 G THAT WAS A fill, could not g II @ 7863'. Bott bing. POOH wi	its., 2 3/8" ACID CUT O et accurate o om	N THE OUTSIDE depth.		
14. I hereby certify that the foregoing is	Electronic Submission #	11562 verifie	by the BLM Wel	I Information	System /	ej 7	
	For COI Committed to AFMSS f	NOCO INC., se for processing	nt to the Farmin by Matthew Hall	gton pert on 06/06/	₹ -		
Name (Printed/Typed) DEBORAF	H MARBERRY		-	TTING CON	V		
					\ o_i	A. A. S.	
Signature (Electronic S	Submission)		Date 05/28/2	002	<u>``</u>		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By 19 10 10 10 10 10 10 10 10 10 10 10 10 10			Title		Date		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to project	itable title to those rights in the	not warrant of subject lease	Office		JUN 1 9 TOT2		
Title 18 U.S.C. Section 1001 and Tyle States any false, fictitious or fraudine its	U.S.C. Section 1212, make it a tatements or representations as	crime for any per to any matter wit	son knowingly and hin its jurisdiction.	willfully to ma	ake to any department or	agency of the United	
ਲੇY ** ORIGINAL **	ORIGINAL ** ORIGIN	AL ** ORIGI	NAL ** ORIG	INAL ** OR	IGINAL ** ORIGIN	NAL **	

Additional data for EC transaction #11562 that would not fit on the form

32. Additional remarks, continued

@ 7894'. POOH 2:52 jts of 2 3/8" tubing with Hallib Baler. SHUT DOWN 5/1/2002 Check well pressure. Csg - 210 psi. Blow well down. RIH with MS, SN and 2 3/8" tubing. Land tubing. Rig up to swab. Make 1 run and swab hung up, parted sand line. POOH with 2 3/8" tubing with sand line and sinker bars. Had sand around swab cup's. SHUT DOWN 5/2/2002 Check well pressure. Csg - 205 psi. Blow down and kill well. RIH with Mule Shoe Collar, SN and 247 jts of 2 3/8" tubing. Make swab run, tubing is clear. Land 2 3/8" tubing @ 7748'. NDBOP & NUWH. SHUT DOWN FINAL REPORT.

BY MIT

Mf

. The AT