UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Noti	ces and Reports on Wells.			
1. Type of Well GAS	0.0 10 10 10 10 10 10 10 10 10 10 10 10 10	5. 6.	Lease Number SF-080516 If Indian, All. or Tribe Name	
2. Name of Operator		7.	Unit Agreement Name	
BURLINGTON				
DECOUDEE	G GAS COMPANY	8.	San Juan 28-5 Unit Well Name & Number	
6. Address & Phone No. of Operator PO Box 4289, Farmington, NM		9.	San Juan 28-5 U #97N API Well No. 30-039-25956 Field and Pool Blanco MV/Basin DK	
4. Location of Well, Footage, Sec 490'FSL, 395'FEL, Sec.14, T-28		, 10.		
NSL-4099, DHC-2020	ti Neito 수	11.	County and State Rio Arriba Co, NM	
subject well. The n	Type of Action Abandonment X Change Recompletion New Cor Plugging Back Non-Rou Casing Repair Water S X Altering Casing Convers Other -	of Pl nstruc ntine Shut o sion t	ans tion Fracturing ff o Injection ement of the	
Casing Program: Hole Size Depth In: 12 1/4" 0-600		<u>ıt</u>	Grade H-40	
Cementing Program:				
calcium chloride (5 WOC 12 hours. Test 14. I hereby certify that the	8 sx Class "B" cement with 0.25 564 cu.ft. of slurry, 200% exces casing to 600 psi/30 minutes. foregoing is true and correct. (KAS)Title Regulatory Administ	s to d	circulate to surface).	
nc (This space for Federal or State APPROVED BY CONDITION OF APPROVAL, if any:	Office use)	te _		