Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	M APPR	6ve	D	
Budget Bur	eau Mo.	100	04-0135	,
Expires:	March	31,	1993	

5. Lease Designation SUNDRY NOTICES AND REPORTS ON WELLS SF078500A Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposals -7. If Unit or CA, Agreement Designation 1. Type of Well 8. Well Name and No. ☐ Well Other 68 San Juan 28-7NP 2. Name of Operator 9. API Well No. Gail M. Jefferson, Rm 1942 **Amoco Production Company** 3003960071 3. Address and Telephone No. (303) 830-6157 10. Field and Pool, or Exploratory Area P.O. Box 800, Denver, Colorado 80201 Blanco Mesaverde 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Sec. 31 T 28N R 7W Unit B 1650'FEL 990' FNL **New Mexico** Rio Arriba CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment **New Construction** Notice of Intent Recompletion Non-Routine Fracturing Plugging Back Water Shut-Off Casing Repair Subsequent Report Altering Casing Other Bradenhead Repair Dispose Water Final Abandonment Notice (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) The Bradenhead repair for this well was completed as follows: MIRU 2/9/95. set tbg plug at 4100', blew down tbg. Set pkr 1 joint deep, bradenhead blew down immediately. TOH w/tbg & pkr, set rbp at 2005' and pres test csg to 1000#'. Csg held press. Installed new seals to stop communication w/bradenhead TOH w.RBP . TIH w/tbg set at 4769 ' . 2jts of pitted tbg was replaced. Tested bradenhead 2/16/95 32 runs for a total of 72 bbls recovered, flowed for 30 min, recovered 5 bbls (total load = 88.5 bbls, LTR=11 1/2 bbls). 2/17/95 BH = 0, Csg = 350 psi, unseat BP and TOH; ;TIH w/tbg to 4741'n w/SN on bottom. 14. I hereby certify 03-03-1995 **Business Assistant** (This space for Federal or State office use Conditions of approval, if any: Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any fall the United States and fall the