

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B 11125.49	
7. Unit Agreement Name	
8. Farm or Lease Name	
Brookhaven Com C	
9. Well No.	
4	
10. Field and Pool, or Wildcat	
So. Blanco P.C.	
11. Elevation (Show whether DF, RT, GR, etc.)	
6225' G.L.	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
El Paso Natural Gas Company	Brookhaven Com C
3. Address of Operator	9. Well No.
P. O. Box 990, Farmington, New Mexico 87401	4
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER L, 1700 FEET FROM THE South LINE AND 840 FEET FROM	So. Blanco P.C.
THE west LINE, SECTION 36 TOWNSHIP 27N RANGE 8W NMPM.	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
6225' G.L.	San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Report on Plug & Abandonment Procedure (June 19-21, 1979)

Circulated fresh water thru tubing and out casing to clean out hole.

Squeezed open hole section with 21 sx. of cement and created cement plug from 2200-2400 ft. (25 cu. ft.)

Waited on cement for two hours.

Perforated casing at 1469'. Spotted 33 sx. of cement through perforations creating a 100' cement plug (1369-1469) covering the Ojo Alamo.

Waited on cement for two hours.

Circulated fresh water for 20 minutes.

Perforated @ 290'. Spotted 84 sx (99 cu. ft.) Cement plug across the perforations. Waited 18 hours for cement to dry.

Spotted a 10 sx. (12 cu. ft.) cement plug at surface and installed a dry hole marker.

Plans for removing debris and renovating the location are being finalized.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gholsom TITLE Production Engineer DATE 6-27-79

Original Signed by CHARLES GHOLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JAN 13 1987
OIL CON. DIV.
DIST. 3

JAN 13 1987