Form	9-331
(May	1963

Form 9-331	t	INITED STATES	SUBMIT IN TRIPLICATE*	Budget Bureau No. 42-R1424.		
May 1963	DFPARTM	IENT OF THE INTER	IOR (Other instructions on re-	5. LEASE DESIGNATION AND		
		EOLOGICAL SURVEY		NM-03603-A		
			0)1,145110	6. IF INDIAN, ALLOTTEE OF	R TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						
ī.				7. UNIT AGREEMENT NAME		
OIL	GAS X OTHER				<u> </u>	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME			
R & G Drilling Company, Inc.			Hammond			
3. ADDRES	SS OF OPERATOR			9. WELL NO.		
	1775 Broadw	av New York	c, N. Y. 10019	47		
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OR WILDCAT			
See al:	so space 17 below.) rface			Mesa Verde-Dakota		
1850 FSL, 1650 FWL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA				
	1030 12	,		35 T27N-R8W		
14. PERMI	4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE			
			6225	San Juan N.M.		
16,	Check An	propriate Box To Indicate	Nature of Notice, Report, or C)ther Data		
			JENT REPORT OF:			
		 1		REPAIRING WE	т.т.	
TEST		PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CASI		
FRAC		IULTIPLE COMPLETE	SHOOTING OR ACIDIZING	- ABANDONMENT		
SHOO		ABANDON*	(Other) (dual completion)			
REPA	IR WELL	CHANGE PLANS	(Other) (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
Oth			1 1 1 1 day postinger dates	including estimated date	of starting any	
pro	RIBE PROPOSED OR COMPLETED OPE oposed work. If well is direction to this work.) *	nations (Clearly state an pertine mally drilled, give subsurface loc	ent details, and give pertinent dates, eations and measured and true vertice	ıl depths for all markers a	ind zones perti-	
	This Blanco Me	esa Verde - Basi	n Dakota, dual com	pletion, was		
	plugged pursua	ant to Oil Commi	ssion Order No. R-	4820.		
	While attempt	ing to squeeze l	00 sacks of neat c	ement into		
	Dakota perfora	ations, approxim	ately 50 sacks of	cement was		
	inadvertently	squeezed into M	esa Verde perforat	ions -		
	-					

cement top 4,000'.
Both sides of this dual completion are now plugged.



SIGNED (Giff)	rue and correct	President	DATE 10-11-74	
(This space for Federal or State office	use)			
APPROVED BY	TITLE		DATE	