Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

FORM APPROVED					
Budget B	ireau No.	1004-0135			
Expires	November	30, 2000			

BUREAU OF LAND MANAGEMENT SINDRY NOTICES AND REPORTS ON WELLS DECEMBER

SE 079232

5. Lease Serial No.

Do not use this form for			V1.1	6 If Indian A	llottee or Tribe !	Jama
	proposals to drill or to re- m 3160–3 (APD) for such p	proposals.	·	o. Il littlail, A	motice of Tribe i	vanic
SUBMIT IN TRIPLICATE	- Other instructions on rev	99 MAY 24 erse side	PM 12: 49	7. If Unit or C	A/Agreement, N	ame and/or No
		OZA CAJERYTY	And the second second second second	∴		
Type of Well Oil X Gas Well Other		070 FARMING	110N, NM 	8. Well Name Bolack C L		#9
Name of Operator Cross Timbers Operating Company		-071	WE A			
. Address	3b. Ph	one No inglude grea	code)	9. API Well N 3004506152		
2700 Farmington Ave., Bldg. K. Ste		401	4000		Pool, or Explora	tory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description of Well (Footage, Sec., T., R., M., or Survey Description)		7 JUN -	4 (850	S. Blanco Blanco Mes		Cliffs
1,650' FNL & 990' FEL Sec 31, T	27N, R08W	onn 1918 E	a. Kiilik	11. County or		
1,050 THE & 950 TEE Sec 51, T	2711, 10011	Dan Year		San Juan	,	NM
12. CHECK APPROPE	RIATE BOX(ES) TO INDICAT	E NATURE OF N	OTICE, REPOR		ATA	
TYPE OF SUBMISSION		TY	PE OF ACTION	I		
Notice of Intent	Acidize	Deepen	Producti	on (Start/Resume)	Water St	ut-Off
	Alter Casing	Fracture Treat	Reclama	,	Well Inte	
X Subsequent Report			Ħ			grity
	Casing Repair	New Construction	Recomp			
Final Abandonment Notice	Change Plans	Plug and Abandon		rily Abandon	DHC Work	over
	Convert to Injection	Plug Back	Water D	isposal		
determined that the final site is ready for final inspection	Notices shall be filed only after on.)	all requirements, in	cluding reclamation	new interval, a Fo on, have been con	mpleted, and th	e operator h
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI	DHC workover operation/wtr. TOH w/95 jts 1 PU & TIH w/csg scra H w/scraper & tbg. TIH tbg. Landed EOT @ 4 RU hot oil trk. Ppd	on of the about -1/4" tbg. (pper & tbg. H w/production, 317' KB. NI 90 bbls hot	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr	ed well on 5 elevators & @ 4,430'. follows: mu WH. RU swa	/21/99. slips. R No fill a le shoe, S b. RIH w/	e operator had been been been been been been been bee
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd	DHC workover operation/wtr. TOH w/95 jts 1 PU & TIH w/csg scrain w/scraper & tbg. TIH tbg. Landed EOT @ 4 RU hot oil trk. Ppd. wabbed 0 BO, 67 BLW in	on of the about -1/4" tbg. (aper & tbg. H w/production, 317' KB. NI 90 bbls hot I	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr	elevators & @ 4,430'. follows: mu WH. RU swa tbg. RDMO	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	deleased above SN & 136 aswab.
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI 5/21/99 MIRU swabbing unit. Sw solvent & inhibitor. Flushed w/ to production selling gas.	DHC workover operations/ DHC workover operatio	on of the about -1/4" tbg. (aper & tbg. H w/production, 317' KB. NI 90 bbls hot I	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr	elevators & @ 4,430'. follows: mu WH. RU swa tbg. RDMO	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	deleased above SN & 136 aswab.
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI 5/21/99 MIRU swabbing unit. Sw solvent & inhibitor. Flushed w/to production selling gas.	DHC workover operations/ DHC workover operatio	on of the about 1/4" tbg. (pper & tbg. H w/productive, 317' KB. NI 90 bbls hot line of the sales w/state.	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr	ed well on 5 elevators & @ 4,430'. follows: mu WH. RU swa n tbg. RDMO	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	deleased above SN & 136 Swab.
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI 5/21/99 MIRU swabbing unit. Sw solvent & inhibitor. Flushed w/ to production selling gas.	DHC workover operations/ I/wtr. TOH w/95 jts 1 PU & TIH w/csg scrains/ I w/scraper & tbg. TIM I tbg. Landed EOT @ 4 IRU hot oil trk. Ppd Ivabbed 0 BO, 67 BLW in 15 bbls wtr. KO well	on of the about 1/4" tbg. (pper & tbg. H w/productive, 317' KB. NI 90 bbls hot line of the sales w/state.	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr uns). Trea wabbing uni	ed well on 5 elevators & @ 4,430'. follows: mu WH. RU swa n tbg. RDMO	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	deleased above SN & 136 aswab.
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI 5/21/99 MIRU swabbing unit. Sw solvent & inhibitor. Flushed w/ to production selling gas. 4. 1 hereby certify that the foregoing is true and correct Name (Printed/Typed)	DHC workover operations/ I/wtr. TOH w/95 jts 1 PU & TIH w/csg scrains/ I w/scraper & tbg. TIM I tbg. Landed EOT @ 4 IRU hot oil trk. Ppd Ivabbed 0 BO, 67 BLW in 15 bbls wtr. KO well	all requirements, in on of the above. -1/4" tbg. (aper & tbg. H w/production, 317' KB. NI 90 bbls hot line of the sales w/single o	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr uns). Trea wabbing uni	ed well on 5 elevators & @ 4,430'. follows: mu WH. RU swa n tbg. RDMO	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	deleased above SN & 136 aswab.
Cross Timbers has completed the 5/19/99 MIRU PU. Killed well w model "G" pkr. TOH w/tbg & pkr. PBTD. SDFN. 5/20/99 Killed well w/wtr. TOH jts 2-3/8", 4.7#, J-55, EUE, 8rd Tagged paraffin plug in tbg. MI 5/21/99 MIRU swabbing unit. Sw solvent & inhibitor. Flushed w/ to production selling gas. 4. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	DHC workover operation/wtr. TOH w/95 jts 1 PU & TIH w/csg scra W/scraper & tbg. TIH tbg. Landed EOT @ 4 RU hot oil trk. Ppd Wabbed 0 BO, 67 BLW in 15 bbls wtr. KO well	all requirements, in on of the above. -1/4" tbg. (aper & tbg. H w/production, 317' KB. NI 90 bbls hot line of the sales w/single o	ve mentione Chng'd out Tagged PBTD on tbg as f D BOP. NU KC1 wtr dwr uns). Trea wabbing uni	d well on 5 elevators & @ 4,430'. follows: mu WH. RU swa whited well w/ t. RDMO SU	/21/99. slips. R No fill a le shoe, S b. RIH w/ PU.	e operator had eleased above SN & 136 (swab.