

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State *g.c.t.* Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name Huerfano Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name <i>Huerfano Unit</i>
3. Address of Operator Box 990, Farmington, New Mexico	9. Well No. 17
4. Location of Well UNIT LETTER G 1550 FEET FROM THE North LINE AND 1550 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 27N RANGE 10W N.M.P.M.	10. Field and Pool, or Wildcat West Kutz P. C.
15. Elevation (Show whether DF, RT, GR, etc.) 6047' DF	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to non-commercial production, it is intended to plug and abandon this well in the following manner:

Squeeze open hole w/50 sacks of cement through a cement retainer.

Spot 30 sack plug in casing from 850' - 1050'.

Spot 30 sack plug in casing from 300' - 500'.


Put 4" x 4' plug and abandonment marker in surface casing w/5 sacks of cement.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original signed by
Carl E. Matthews

SIGNED _____

TITLE **Petroleum Engineer**



APPROVED BY *Ernest Cleveland*

TITLE *Supt Dist III*

DATE *3-29-66*

CONDITIONS OF APPROVAL, IF ANY: