

1. NAME OF WELL: San Juan

2. LOCATION OF WELL: San Juan, New Mexico

3. OWNER: Hanson B

4. DATE OF NOTICE: 3-20-68

5. TYPE OF WELL: Oil

6. DEPTH OF WELL: 25, 27-X, 13-W

7. COUNTY OF PARISH: San Juan STATE: New Mexico

8. ELEVATION (SHOW WHETHER ON, IN, OR, ETC.): 5965' GL

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREATMENT	☐	FRACURE TREATMENT	☐
SHOOTING OR ACIDIZING	☐	SHOOTING OR ACIDIZING	☐
REPAIRING WELL	☐	REPAIRING WELL	☐
PUTTING OR ALTER CASING	☐	PUTTING OR ALTER CASING	☐
MULTIPLE COMPLETE	☐	MULTIPLE COMPLETE	☐
ABANDON*	☒	ABANDON*	☐
CHANGE PLANS	☐	CHANGE PLANS	☐

(NOTE: Report results of multiple completion or Well Completion or Recombination Report (See Form 100-100))

11. Describe in detail the completion or abandonment (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work, and when the well is directionally drilled, give surface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

(Est. date to start work 4-1-68)

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations.
3. Shoot pipe loose at free point and pull.
4. Spot 100' cement plug 50' in and 50' out of stub.
5. Spot 100' cement plug across top of picture cliff.
6. Spot 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.

RECEIVED

MAR 29 1968

U. S. GEOLOGICAL SURV
MINING DIVISION



12. I hereby certify that the foregoing is true and correct

SIGNED: John Payne TITLE: Agent DATE: 3-20-68

(Signature of Owner or State official)

SIGNED: _____ TITLE: _____ DATE: _____

(Signature of Approval, if any)