Form 3160-5 November 1983) (Formerly 9-331)

NAME OF OPERATOR

14.

R & G DRILLING COMPANY

P. O. Drawer 419

3. ADDRESS OF OPERATOR C/O Walsh Engr. & Prod. Corp.

1670'FSL, 790'FEL

UNITED STATES DEPARTMENT OF THE INTERIOR verse side)

SUMMIT IN TRIPLICATE.

orm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO. NM-03603-A

7. UNIT AGREEMENT NAME

S. FARM OR LEASE NAME

Hammond

40

10. FIELD AND POOL, OR WILDCAT

Sec. 26-T27N-R8W N.M.P.M.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Blanco Pictured Cliffs So.

9. WELL NO.

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See niso space 17 below.)
At surface

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

Farmington, New Mexico 87499

d. IF INDIAN, ALLOTTEE OR TRIBE NAME

| 15. ELEVATIONS (Show whether D | F, RT, GR. etc.) | 2. COUNTY OR PARISH: 13. STATE San Juan N.M. |
|--------------------------------|--|--|
| | Nature of Notice, Report, or Oth | |
| ICE OF INTENTION TO: | BUBBEQUEN | T REPORT OF: |
| PULL OR ALTER CASING | WATER SHUT-OFF | REPAIRING WELL |
| MULTIPLE COMPLETE | FRACTUBE TREATMENT | ALTERING CASING |
| ABANDON* | SHOOTING OR ACIDIZING | ABANDONMENT* |
| CHANGE PLANS | (Other) | |
| prary Abandonment x: | (Norr: Report results of Completion or Recompletic | multiple completion on Well on Report and Log form.) |
| | Check Appropriate Box To Indicate I ICE OF INTENTION TO: PULL OR ALTER CASING MILLTIPLE COMPLETE ABANDON* CHANGE PLANS | Check Appropriate Box To Indicase Nature of Notice, Report, or Oth ICE OF INTENTION TO: PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS (Other) |

It is requested that temporary abandonment of the well be approved for one (1) year. Also that the well be approved to leave in current condition for the one (1) year. The reasons for the request are:

- The Pictured Cliffs has such a low productivity that the well will not produce in paying quantities.
- Other wells in area are being recompleted in the Fruitland Coal.
- Additional time is required to evaluate the well for possible potential production in the Fruitland Coal.

| APRO 4 1990 THIS APPROVAL EXPIRES JAN 0 1 OIL CON. DIV. DIST. 3 | SECUIVED THE PROPERTY OF |
|---|--|
| FOR: R & G DRILLING COMPANY 18. I hereby certify that CRIGINAL SIGNED BY correct SIGNED | 2 3 3 2 1/3/90 |
| EWell N. Walsh (This space for Federal or State office use) APPROVED BY | Ken Townsend |
| *See Instructions on Reverse Side | FOR THE STATE OF T |