trorm:	9-331 a
(Feb	. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa 6				
Lease No	% 03603 A			
Unit				

SUNDRY NOTICES AND REPORTS ON WELLS

	II	
OTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1613
OTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	1 1
OTICE OF INTENTION TO TEST WATER SHUT-OFF		t B
OTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
OTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	. 1
	SUPPLEMENTARY WELL HISTORY	
OTICE OF INTENTION TO ABANDON WELL		
(INDICATE ABOVE BY CHECK MARK NA	TURE OF REPORT, NOTICE, OR OTHER DATA)	
	December 29	, 19 <u>5</u> 8
Harmond ell No. 2 is located 1700. ft. from	$\frac{N}{S}$ line and 1650 ft. from $\frac{E}{W}$ line of se	ec. 26
(1/4 Sec. and Sec. No.) (Twp.) (Ra		A.
o. Blanco FC Ear Just (County or Su	abdivision)	
e elevation of the derrick floor above sea level	تعاقب ماري اللها الا يصول	
DETAILS	S OF WORK OIL CON. CO	M./
ite names of and expected depths to objective sands; show sizes, v ing points, and all other	weights, and lengths of proposed calings; is dispernutiling	igos, cement-
It is proposed to F & A this To run tubing to bottom and 200 in casing. Check after To pump approx 25 sacks down between production and surfa To place marker and clean up	circulate cement to approx act. n 5° and some amount down ace casing. p location.	
This well has poor casing-caused well is being drilled.	minot be recovered and new	
I understand that this plan of work must receive approval in writ	•	mmenced.
mpany John A. Lean		*
dress 20x 1200	0	
	Original Signed	
Farmington, New Merico	By John A. Egan	
	Title Operator	

