Form	9-881 a
(Feb.	1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budg Appr	get Bureau No. 42-R358.4. oval expires 12-31-60.
and Office	Sexta Po
ense No.	G60/10
	Esserfero Unit

I WOLLCE OF	INTENTION TO DOLL		GURGEOUGUE	DEPORT OF THE	MAI S	105
NOTICE OF	NOTICE OF INTENTION TO DRILL			SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
	INTENTION TO TEST WAT			REPORT OF ALTERIN	14 1 141 47 47	7 ÷ 1
NOTICE OF	INTENTION TO RE-DRILL	OR REPAIR WELL	1 1	REPORT OF RE-DRIL		
NOTICE OF	INTENTION TO SHOOT OF	R ACIDIZE	1 11	REPORT OF ABANDO	• •	Ā
NOTICE OF	INTENTION TO PULL OR	ALTER CASING	SUPPLEMENTA	RY WELL HISTORY		
NOTICE OF	INTENTION TO ABANDON	WELL				
	(INDICA	TE ABOVE BY CHECK MA	RK NATURE OF REPORT	, NOTICE, OR OTHER	DATA)	
	·					
				120	maker 20	., 19.
7 11 5 7	89	. 1500	(N)	1013.2.	(F .)	20
Vell No	is locat	ted ft. fro	m ine and	1.03.3 ft. fro	m line of sec.	29
il Suct	ion 2)	278	LW	13011	• ,	
	ec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
r. Autr	P.C. Ext.		See Jues		New Mexico	
	(Field)	(Count	y or Subdivision)	•	(State or Territory)	
ate names	of and expected depths to	o objective sands; show ing points, and al	sizes, weights, and leng Il other important prop	ths of proposed casi: losed work)	ngs; indicate mudding jo	bs, ceme
lhis w	ll was plugged	and chandras	d in the fall	cving muno	r:	
1 h	ent plug from	1756_1520 ett	h Mi sacka.			
	and pulled 21			•		
		750' - 630' W				
2. Cut 3. Ces		EFF - SETTINGS	with 25 and	图 。		
2. Out 3. Cen 4. Cen	mert play from		marker with standard			
2. Out 3. Cen 4. Cen			A WARE WAY SECURE			
2. Out 3. Cen 4. Cen	mert play from		. a su passe may succeed			
2. Out 3. Cen 4. Cen	mert play from					
2. Out 3. Cen 4. Cen	mert play from					
2. Out 3. Cen 4. Cen	mert play from					
2. Out 3. Com k. Com 5. Set	met plug from A' x A' pipe	es mariner.	•	ogical Survey before	operations may be comm	enced.
2. Out 3. Com 5. Com 5. Set	nd that this plan of work	es mariner.	in writing by the Geole	ogical Survey before	operations may be comm	enced.
Lundersta	nd that this plan of work	must receive approval	in writing by the Geole	~		
2. Cat 3. Com 5. Set I understar	next plug from A' x 4" pipe nd that this plan of work El Faso Hatu Box 997	must receive approval	in writing by the Geole	~	operations may be comm	
2. Cat 3. Com 5. Set I understar	nd that this plan of work	must receive approval	in writing by the Geole	Origina	Signed EWELL N.	
2. Cat 3. Com 5. Set I understar	next plug from A' x 4" pipe nd that this plan of work El Faso Hatu Box 997	must receive approval	in writing by the Geole	G riginal	Signed EWELL N.	
2. Out 3. Com 4. Com 5. Set	next plug from A' x 4" pipe nd that this plan of work El Faso Hatu Box 997	must receive approval	in writing by the Geole	G riginal	Signed EWELL N.	

U.S. GOVERNMENT PRINTING OFFICE: 1956-O-35 3560

