Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

DEPARTME BUREAU OF

35

UNITED STATES	FORM APPROVED
ARTMENT OF THE INTERIOR ALL OF LAND MANAGEMENT	Budget Bureau No. 1004-013 Expires: March 31, 1993

SUNDRY NOTICES AND RE Do not use this form for proposals to drill or to dee Use "APPLICATION FOR PERMIT	ppen or reentry to a different reservoir.	5. Less Designation and Serial No. SF-079232 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation
:		7. If One or CA, Agreement Designation
1. Type of Well Oil Ges Well Other		8. Well Name and No.
2. Name of Operator AMOCO PRODUCTION COMPANY	Attention: WAYNE BRANAM, RM 1220	BOLACK C LS #2 9. API Well No.
3. Address and Telephone No.	(303) 830-4912	3004506279 10. Field and Pool, or Exploratory Area
P.O. Box 800, Denver, Colorado 80201 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		BLANCO PICTURED CLIFFS SOUTH
800 FNL 1180FWL Sec. 3	28 T 27N R 8W UNIT D	11. County or Parish, State SAN JUAN NEW MEXICO
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Other (Note: Reg	Conversion to Injection Dispose Water port results of multiple completion on Well Completion or tion Report and Log form. }
13. Describe Proposed or Completed Operations (Clearly state all pertinent det subsurface locations and measured and true vertical depths for all market AMOCO PROPOSES TO PLUG AND ABANDON	rs and zones pertinent to this work.)"	PROCEDURES. 94 SEP 15 ALTI
14. I hereby certify that title foregoing is true and correct Signed Signed	TitleBUSINESS AI	NALYST Date 09-07-1994
(This space for Federal or State office use) Approved by Conditions of approvel, if any: Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and	Title Title	Date
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and	willfully to make to any department or agency or the United St	4004

* See Instructions on Reverse Side

L DISTRICT MANAGER

PXA Procedures Bolack C LS #2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. Pull out of hole with 1" tbg. RIH with 2 3/8" workstring and cement retainer, set retainer at 2100'. Test casing integrity to 500#.
- 4. Pump into open hole establishing rate and pressure. Squeeze open hole with 62.667 cuft cement. (100% excess). Pull out of retainer and spot cement plug to 1200' with 306.885 cuft cement. Load hole with wellbore fluid to 367'.
- 5. RIH with perf gun and shoot squeeze holes at 367' and circulate to surface with 110.32 cuft cement. Pull out of hole and displace cement to surface with 125.129 cuft cement.
- 6. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 7. Turn over to John Schwartz for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

