For (I	m 9-	<b>331 a</b> 351)	
			 X

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No.	078105
IDAJE (	(E. 1)
Die C	
(c.	

المراجع المحاجم المحاجم

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	i 🔻 li
(INDICATE ABOVE BY CHECK	MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
I.M. Pederal "J"	<u>December 20</u> , 196
'ell No. 2 is located 790 ft.	from ${R \brack S}$ line and 790 ft. from ${E \brack W}$ line of sec. 23
W/L Sw/L Sec. 25 27% (½ Sec. and Sec. No.) (Twp.)	134 SAPA
	(Range) (Meridian)
	ian Juan New Yex100 county or Subdivision) (State or Territory)
the area of the companies and the companies of the compan	
Equeese Gallup some 5177-89' without off kg esg, 12k2' pulled.	th 20 sacks, plug from 5210' to 5000', him cap Place plug h0 sacks in top of cag. up to 1000 g cag. 320' to 270'. Place h0 sacks, plug to
Squeese Gallup some 5177-89' without off him esg, 1242' pulled.	th 20 sacks, plug from 5210' to 5000', him cap Place plug h0 sacks in top of cag. up to 1000 g cag. 320' to 270'. Place h0 sacks, plug to
Squeese Gallup some 5177-89' without off his esg, 12h2' pulled. Place 20 sacks, plug btm surface of surface cag. 90' to surface &	Place plug ho sacks in top of eag. up to 1000 eag. 320' to 270'. Place ho sacks, plug to set h' marker pipe.  DEC 2 2 1961
Squeese Gallup some 5177-89' without off his esg, 12h2' pulled. Place 20 sacks, plug btm surface of surface cag. 90' to surface &	Place plug ho sacks in top of eag. up to 1000 cag. 320' to 270'. Place ho sacks, plug to set h' marker pipe.  DEC 2 2 1961
Cut off high eag, 1242' pulled. Flace 20 sacks, plug btm surface of surface eag. 90' to surface &	Place plug ho sacks in top of eag. up to 1000; high cap rough to sacks in top of eag. up to 1000; high cap to 270. Place ho sacks, plug top to the marker pipe.  DEC 2 2 1961  Toval in writing by the Geological Survey before operations minuse commenced.
Squeese Gallup sone 5177-89' with off his cag, 1242' pulled. Place 20 sacks, plug btm surface of surface cag. 90' to surface is	Place plug ho sacks in top of eag. up to 1000; high cap rough to sacks in top of eag. up to 1000; high cap to 270. Place ho sacks, plug top to the marker pipe.  DEC 2 2 1961  Toval in writing by the Geological Survey before operations minuse commenced.
Squeese Gallup sone 5177-89' with off his esg, 1242' pulled. Place 20 sacks, plug btm surface of surface esg. 90' to surface is a surface of surface in su	Place plug ho sacks in top of esg. up to 1000 esg. 320' to 270'. Place ho sacks, plug to set h' marker pipe.  DEC 2 2 1961  roval in writing by the Geological Survey before operations mily be commented.  Cil Company