



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC
87410

GOVERNOR
DAVID F. CARGO
CHAIRMAN

LAND COMMISSIONER
ALEX ARMIJO
MEMBER

STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

September 2, 1970

K23-27W-8W

Mr. William C. Russell
1775 Broadway
New York, New York 10019

Dear Mr. Russell:

The bradenhead test which was conducted on your Marron #39 well on August 10, 1970, indicates casing failure as the casing pressure dropped from 258# to 225 # when the bradenhead was flowed for 15 minutes.

You are hereby directed to take immediate remedial action to repair the casing in this well. Please submit your plan of repair to this office for approval prior to commencing operations.

Yours very truly,

Emery C. Arnold
Emery C. Arnold
Supervisor, District #3

ECA:mc

cc: Oil Conservation Commission
Box 2088
Santa Fe, New Mexico

U. S. G. S.
Box 959
Farmington, New Mexico