



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Farmington
Lease No. 078089
Unit Govt Scott

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Running Surface Casing

X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 26, 1956

Govt Scott

Well No. 5 is located 1650 ft. from SW line and 1650 ft. from W line of sec. 23NE, SW, Sec. 23 27N 11W NM PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)West Kutz San Juan County NEW MEXICO
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 6392 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled to 107' KB. Reamed 8 5/8" hole to 13 3/4" hole to 107' KB. Ran 9 5/8" Armco, 32.3#, H-40 Casing landed at 104' KB and cemented w/90 sax ideal cement. Pumped plug to 9' KB. Waited 24 hours, drilled out cement and tested w/500# for 30 minutes. Held OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The British-American Oil Producing CompanyAddress Box 180Denver, ColoradoBy Thomas M. Hogan
Title District Superintendent