

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  **Federal** Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator <b>El Paso Natural Gas Company</b> 3. Address of Operator <b>Box 990, Farmington, New Mexico</b> 4. Location of Well UNIT LETTER <b>E</b> , <b>1750</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>West</b> LINE, SECTION <b>20</b> TOWNSHIP <b>27N</b> RANGE <b>9W</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>6366' GL</b>	7. Unit Agreement Name 8. Farm or Lease Name <b>Denman</b> 9. Well No. <b>1</b> 10. Field and Pool, or Wildcat <b>Fulcher Kutz P. C.</b> 12. County <b>San Juan</b>
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <b>Workover, Case and Frac</b> <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER _____ <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In order to increase production it is planned to workover and restimulate this well in the following manner:

Pull tubing and clean out to 2390'.

Run a full string of 2 7/8" casing and cement with approximately 50 sacks of cement.

Selectively perforate and sand water fracture the Pictured Cliffs formation.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By:

SIGNED L. O. Van Ryan TITLE Petroleum Engineer DATE 10-21-69

APPROVED BY *Emmyl...* TITLE *Sup Dist III* DATE 10-23-69

CONDITIONS OF APPROVAL, IF ANY: