(SUBMIT IN TRIPLICATE)

Land Office Sente To

Lease No. 078872 A

Unit Eld Sec. 21 is the

UNITED STATES

DEPARTMENT OF THE INTERIOR Designated Drilling unit **GEOLOGICAL SURVEY**

i.	
SUNDRY NOTICES A	AND REPORTS ON WELLS
MOTION OF INTENTION TO DRIVE	SUBSEQUENT REPORT OF WATER SHUT-OFF PRODUCTION
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHOT-OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	11
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MARK	C NATURE OF REPORT, NOTICE, OR OTHER DATA)
Bolack #15	March 12 , 1952
Wall No. 15 is located 990 ft fr	om $\binom{N}{c}$ line andft. from $\binom{E}{c}$ line of sec21
	(
(72.000.000.000.000.000.000.000.000.000.0	(Range) (Meridian)
S.W. Kuts Cenyon (Ext.) San Juan	
(Field) (Count	y or Subdivision) (State or Territory) 6332 Grd.
he elevation of the derrick floor above sea le	
	ILS OF WORK izes, weights, and lengths of proposed casings; indicate mudding jobs, cement-
and semanted at 2002'EB with 75 sac Moved off rottery tools. Moved in cable tools on 1/12/52.	52 CD, 14-H, 8 rd. thd., API, Hational casing iks of regular cement. 1995 of casing in hole. bailed hole dry. Hole stood dry for 30 minute
I understand that this plan of work must receive approval company THE FRONTIER REFINING Conductions Address 410 Boston Bldg.	in writing by the Geological Survey before operations may be commenced.
Denver, Colorado	By Assessment and Assessment

U. S. GOVERNMENT PRINTING OFFICE 10-5487-3