

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
Tribal #14-20-0603-927

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tract #4

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA**Sec. 20, T-27N, R-17W.,
South Table Mesa Area**

12. COUNTY OR PARISH

San Juan

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL
WELL ☐GAS
WELL ☐OTHER ☒**Re-entry of P&A Wildcat**

2. NAME OF OPERATOR

Amerado Petroleum Corporation

3. ADDRESS OF OPERATOR

P. O. Box 1440, Durango, Colorado4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface**NE/4, NW/4, 640' P&A & 1900' P&A Sec. 20, T-27N., R-17W.,
San Juan County, New Mexico**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR - 5313'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/17/68 - Schlumberger perf. 4 1/2" OD csg., Paradox zone from 7000' to 7100' with (1) Hyperjet shot per ft. Halliburton acidized 4 1/2" csg. perfor. from 7000' to 7100' with 1000 gals. of HCl acid, maximum press. 3400#, broke back to 2500#, with acid on formation. Avg. treating press. 2200#, injection rate 2-1/8 bbls. per min., press. dropped to 2000 in 10 min., after pump stopped. Spent well and flowed 1/2 bbl. of water and died. Flushed acid with 24 bbls. of fresh water. Scrubbed and flowed 1-1/2 hrs., 26 bbls. of lead water. 9 hrs. flowed 6.04 bbls. oil and 24.96 bbls. water, thg. press. 1750# to 2000, 19/64" to 32/64" choke, avg. gas. volume 2,031,000 cu. ft. per day. Oil gravity 43.3 at 92 deg.



RECEIVED

MAR 23 1968

U. S. GEOLOGICAL SURV
FACSIMILE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Field Clerk**DATE **3-27-68**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations of Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for special instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1969-O-685229

987-881

