Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

coresentations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

BUREAU OF LAND MANA	AGEMENT	Expires: March 31, 1993
		5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NM-003380
Do not use this form for proposals to drill or to deepen o	r reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT - " fo	r such proposals	
		7. If Unit or CA, Agreement Designation
1. Type of Weil Oil Ges Weil Weil Other		8. Weil Name and No.
	A44	FLORANCE /D/ LS 010
2. Name of Operator AMOCO PRODUCTION COMPANY	Attention: Ed Nicholson	9. API Well No.
	EG MICHOISON	3004506444
3. Address and Telephone No. P.O. Box 800 Denver, Colorado 80201	(303) 830-5014	10. Field and Pool, or Exploratory Area
		BLANCO-MESAVERDE
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
790' FNL 1650'FEL Sec. 17	7 27N R 8 W	
		SAN JUAN NEW MEXICO
12. CHECK APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		
1. (4) (4) (6) (7)		
	Abandonment [Change of Plans
Notice of Intent	Recompletion	New Construction
Subsequent Report APR 2 1993	Plugging Back	Non-Routine Fracturing
(8) 37	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection
	7 ' '	Dispose Water
Final Abandonment Norfc 1	_ Other	Dispose evecer
Final Abandonment Notice CON. DIV.	(Note: R	eport results of multiple completion on Well Completion or
DIST. 3	(Note: R Recomp	eport results of multiple completion on Well Completion or letion Report and Log form. }
DIST. 3	(Note: R Recomp	eport results of multiple completion on Well Completion or letion Report and Log form. }
DIST. 3	(Note: R Recomp	eport results of multiple completion on Well Completion or letion Report and Log form. }
DIST. 3	(Note: R Recomp	eport results of multiple completion on Well Completion or letion Report and Log form. }
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z	(Note: R Recomp I give pertinent dates, including estimated date of star ones pertinent to this work.)*	eport results of multiple completion on Well Completion or letion Report and Log form. } ting any proposed work . If well is directionally drilled, give
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z	(Note: R Recomp If give pertinent dates, including estimated date of star ones pertinent to this work.)* If the received approval to modify procedure	eport results of multiple completion on Well Completion or letion Report and Log form. I ting any proposed work . If well is directionally drilled, give to due to excessive cement volumes -
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and 2 MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM and DELM and appropried the representations. Blend used on the	(Note: R Recomp It give pertinent dates, including estimated date of star sines pertinent to this work.)* d received approval to modify procedure tion was 65/35 blend with 2% GEL. Till	eport results of multiple completion on Well Completion or letion Report and Log form. 1 ting any proposed work. If well is directionally drilled, give the due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to
13. Describe Proposed or Completed Operations Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z MIRUSU on 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 2489.	(Note: R Recomp I give pertinent dates, including estimated date of star ones pertinent to this work.)* d received approval to modify procedure job was 65/35 blend with 2% GEL. TH 9' to 2100', TOH TBG, TIH w/wire line,	eport results of multiple completion on Well Completion or letion Report and Log form. 1 ting any proposed work. If well is directionally drilled, give e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH of 49 sks cmt to 1844'. TOH to
13. Describe Proposed or Completed Operations Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 9' to 2100', TOH TBG, TIH w/wire line, and the sks cmt below retainer, pull out, spondard to many and est rate.	eport results of multiple completion on Well Completion or letion Report and Log form. 1 ting any proposed work. If well is directionally drilled, give e due to excessive cement volumes H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH to 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'.
13. Describe Proposed or Completed Operations Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 9' to 2100', TOH TBG, TIH w/wire line, y DN TBG. Attempt to pmp and est rate solutions.	eport results of multiple completion on Well Completion or letion Report and Log form. 1 ting any proposed work. If well is directionally drilled, give edue to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH of 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. Industrial to the complete com
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH lay Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 9' to 2100', TOH TBG, TIH w/wire line, y DN TBG. Attempt to pmp and est rate solutions.	edue to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmb out P&A marker. Prepare to
13. Describe Proposed or Completed Operations Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 9' to 2100', TOH TBG, TIH w/wire line, y DN TBG. Attempt to pmp and est rate solutions.	eport results of multiple completion on Well Completion or letion Report and Log form. I ting any proposed work. If well is directionally drilled, give the due to excessive cement volumes -H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH to the through csg leaks 150' to 200'. To the through csg leaks 150' to 200'. The perf w/4 shots at 2100', TOH to through csg leaks 150' to 200'. The perf w/4 marker. Prepare to The performance to The performance of t
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and z MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM and BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH lay Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93.	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 100 sks cmt below retainer, pull out, sports of TOH wireline, pmp to est rate. Mix a csg, top off full. Cutoff WH and install	egort results of multiple completion on Well Completion or letion Report and Log form. 1 ting any proposed work. If well is directionally drilled, give the due to excessive cement volumes -H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH to 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH lay dn 15 jts, reverse out, spot 81 sks mud at 1844' to 250', TOH lay Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93.	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 100 sks cmt below retainer, pull out, sport DN TBG. Attempt to pmp and est rate of the csg, top off full. Cutoff WH and install and Ron Snow BLM Rep on site, the original sport of the company of the company of the company of the csg.	edue to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmi out P&A marker. Prepare to
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and 2 MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM and BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a	d received approval to modify procedure job was 65/35 blend with 2% GEL. The polyton of the procedure is to the procedure in the procedure is to the procedure in the procedure is to 2100', TOH TBG, TIH w/wire line, 100 sks cmt below retainer, pull out, spoy DN TBG. Attempt to pmp and est rate is csg, top off full. Cutoff WH and install and Ron Snow BLM Rep on site, the original Halliburton, we were able to design and Halliburton, we were able to design a	edue to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmb out P&A marker. Prepare to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at	d received approval to modify procedure job was 65/35 blend with 2% GEL. The procedure job was 65/35 blend with 2% GEL.	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmb out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and subsurface locations and measured and true vertical depths for all markers and 2 MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM and BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe original sky control of the procedure job was 65/35 blend with 2% GEL. The procedure job	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at	d received approval to modify procedure job was 65/35 blend with 2% GEL. The procedure job was 65/35 blend with 2% GEL.	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe 100 sks cmt below retainer, pull out, spoy DN TBG. Attempt to pmp and est rate to csg, top off full. Cutoff WH and install and Ron Snow BLM Rep on site, the original Halliburton, we were able to design at a much lower cost.	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe object to 2100', TOH TBG, TIH w/wire line, 100 sks cmt below retainer, pull out, specy DN TBG. Attempt to pmp and est rate for, TOH wireline, pmp to est rate. Mix as csg, top off full. Cutoff WH and install and Ron Snow BLM Rep on site, the original Halliburton, we were able to design as a much lower cost.	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe original state of the procedure job was 65/35 blend with 2% GEL. The procedure job was 65	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH to 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU 0n 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at 11 you have any questions please call E. R. Nicholson at 30 and 14.1 hereby certify that the foregoing is true and correct	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe original state of the procedure job was 65/35 blend with 2% GEL. The procedure job was 65	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH tot 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that
MIRUSU On 3/12/93. Called Wayne Townsend at BLM an BLM agreed and approved the revisions. Blend used on the 2489'. TOH lay dn 15 jts, reverse out, spot 19 sks mud 248 wireline, TIH with 7 5/8 retainer set at 2063, mix and pmp 1844' reverse out, spot 81 sks mud at 1844' to 250', TOH la Could not est rate, TIH wireline to 250' perf w/4 shots at 25 braidenhead sd wait for crew to NDBOP check cmt level in RDSUMO on 3/15/93. Note: With prior approval from BLM, Wayne Townsend, a reduce excessive cmt volumes and, with input from BLM a still exceed the BLM quality and control regulations but at If you have any questions please call E. R. Nicholson at 30 minutes.	d received approval to modify procedure job was 65/35 blend with 2% GEL. THe original state of the procedure job was 65/35 blend with 2% GEL. The procedure job was 65	e due to excessive cement volumes - H w/TBG spot 101 sks cmt 2962' to perf w/4 shots at 2100', TOH to 49 sks cmt to 1844'. TOH to through csg leaks 150' to 200'. and pmp 97 sks cmt circ cmt out P&A marker. Prepare to inal procedure was modified to and test some cement blends that

* See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

APPROVED