F m 3110-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

SUNDRY NOTICES	AND	REPORTS ON WELLS
se this form for proposals to d	rill or to	deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT - " for such proposals

5. Lease Designation and Serial No. SF 077974 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation

. Type of Well			
Oil Gase Other		8. Well Name and No.	#2
2. Name of Operator	Attention:	Lodewick 9. API Well No.	# 4
Amoco Production Company	Gail M. Jefferson, RM 1295C	<u> </u>	
3. Address and Telephone No.	(303) 830-6157	3004506	
P.O. Box 800, Denver, Colorado 80201	(303) 830-0137	10. Field and Pool, or Exploratory	
4. Location of Well (Footage, Sec., T. R., M., or Survey Description)		Fulcher Kı	utz PC
	40 T 27N D 0\A/ 11-1-84	11. County or Parish, State	
895FSL 895FWL Se	ec. 18 T 27N R 9W Unit M	San Juan	New Mexico
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER D	DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
	Abandonment	Change of Plans	
Notice of Intent	Recompletion	New Construction	
	Plugging Back	Non-Routine Fracturing	
Subsequent Report	Casing Repair	Water Shut-Off	
	Altering Casing	Conversion to Injection	
Final Abandonment Notice	Other	Dispose Water eport results of multiple completion on	Well Completion or
	(Note: ne Recompl	eport results of multiple completion of letion Report and Log form.)	Ven Completion of
	OHL GUBL. Dist. 8	070 SALVATION, NII 070 SALVATION, NII 070 SALVATION, NII	RECEIVED
14. I hereby certify that the foregoing is true and correct Signed Laul W. Hereby	Title Sr. Admin. S	taff Asst. Date	07-03-1995
(This space for Federal or State office use)			
		ATTHUVEL	
Approved by	Title	AS AMENTO	rl,
Conditions of approval, if any:		HO MINE THE	3.m
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing representations as to any matter with n its jurisdiction.	gly and willfully to make to any department or agency of the United S	(A	nt statements or
	* See Instructions on Reverse Side NMOCD	DISTRICT MANA	CER

Lodewick #2 Orig. Comp. 4/51 TD = 2585', PBTD = ' Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg and lay down. Rig down. Rig up wire line. Set retainer at 2436'. Test casing integrity to 500#. Rig down service unit. Rig up Haliburton and pump cement below retainer to squeeze perfs at 2486' to 2548' with 46 cuft of cement. Drop ball and pump casing volume to fill to surface. (22 cuft cement.)
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 5. Turn over to John Schwartz for reclamation.
- 6. Rehabilitate location according to BLM or State requirements.

LODEWICK 002 198
Location — 18M—27N—9W
SINGLE pc
Orig.Completion — 4/51
Last File Update — 1/89 by BCB



