Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED B. dget Bureau No. 1004-0135 Expires: March 31, 1993

5 Lease Designation and Serial No.

	RTS ON WELLS	6. If Indian, Allottee or Tribe Name	
Do not use this form for proposals to drill or to dee Use "APPLICATION FOR PERMIT"		Navajo	
SUBMIT IN TRIF	14 (1) 1 (1) (1)	7. If Unit of CA, Agreement Designation	
1. Type of Well Oil X Ga: Well Cther 2. Name of Operator Taurus Exploration, U.S.A., Inc. 3. Address and Telephone No. 2198 Bloomfield Highway: Farmington, NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1450' FSL, 1450' FEL, Sec. 13, T27N, R9W NMPM		8 WellName and No. Ramenta etal #1	
		9. API Well No.	
		30 - 045 - 06471 10 Field and Pool, or exporatory Area	
		Basin Dakota	
		11. County or Parish, State	
	DIOATE MATURE OF MOTION REPORT	San Juan NM	
CHECK APPROPRIATE BOX(s) TO IN	DICATE NATURE OF NOTICE, REPOR	T, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTIO	N	
Notice of Intent X Suprequent Report	Abandonment Recompletion Plugging Back	Change of Plans New Construction Non-Rostine Fractions	
Final Abandonment Notice	Casing Repair Altering Casing X Other Change tubing	Water Smit-Off Conversion to Injection Dispose Water (Nete: Report results of milliple completion on Well Completion of Recompletion Report and Log forms)	
give subsurface ocations and measured and true vertical depths for 6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
give subsurface ocasions and measured and true vertical depths for 6/3/98 MIRU. TOH and lay down 217 jts 1 Seating Nipple @ 6435'.	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1 Seating Nipple @ 6435'.	or all markers and zones pertinent to this work.)*		
6/3/98 MIRU. TOH and lay down 217 jts 1 Seating Nipple @ 6435'.	or all markers and zones pertinent to this work.)* 1/4" tubing. Ran 208 jts 2 3/8" 4.		