Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SHINDEY	NOTICES	AND	DEDODTS	CN	WEI	

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5.	Lease	Design	ation	and	Serial	No.
	/	G.				

M\$F	-0	788	372A
------	----	-----	------


Ŀ	If Indian.	Allassa.	ar Talka	Mt

• •	or to deepen or reentry to a different reservoir. PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	L	8. Well Name and No. Alice Bolack No. 12 9. API Well No. 30-045-06553 10. Field and Pool, or exploratory Area Pictured Cliffs 11. County or Parish, State San Juan Co., NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT	, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Marathon Oil Company respectfully potential of the Pictured Cliffs. temporarily abandoned. Listed on a	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other Reactivate or T.A. Il pertinent details, and give pertinent dates, including estimated date of startical depths for all markers and zones pertinent to this work.)* proposes to move onto the Alice Bolack No. If warranted, the well may be tied into a an attached page is a summary of the propose as weather and manpower restraints permit.	12 to determine the producing low pressure system or
(APPROVAL EXPIRES MAY 0 1 1996	DECEMBED JAN 1 6 1986 D OUL COM DOM

. I hereby certify that the foregoing is true and correct Signed	Title _	Advanced Production Engineer	_ Date	12/22/95
(This space for Federal or State office use)				
Approved by	Title _		Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any takes Uctivious or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side



Alice Bolack No. 12 Form 3160-5 Section 13

- 1. MIRU PU. Record pressures of tubing and casing. Bleed pressures to mud pit.
- 2. ND wellhead, and NU BOPE. POOH with 1" tubing. PU 2 3/8" notched collar and RIH on 2 3/8" workstring. Tag reported TD at 2085'. RU swab and swab well to remove wellbore liquids.
- 3. Tie casing into test meter and record gas volumes while swabbing.
- 4. Based on swab results, a decision will be made to connect the No.12 to a low pressure gas sales system, request an additional extension or to temporarily abandon the well.
- 5. If the well is to be temporarily abandoned, the procedure listed below will be conducted.
- 6. RU wireline unit and set 5 ½" CIBP at 1975'. RD wireline unit.
- 7. Load hole with chemically inhibited water.
- 8. Pressure test casing and CIBP to 500 psi for 30 minutes.
- 9. RDMO PU. Report results to BLM.

8 5/5" @ 109'

TOC @ 1,517'CALCULATED

5 1/2" @ 2,028'

1" @ 2,071'

TD @ 2,085'

Marathon Oil Company
Alice Bolack # 12
UL "C" 990' FNL & 1650' FWL
Sec 15, T-27N, R-11-W
San Juan County, New Mexico
API# 30-045-06553
Federal Ls. # NMSF 078872A

GL: 6239' KB: 6303' TD: 2085' PBTD: 2085'

Surface Casing: 8 5/8" @ 109' 24.7#, Cement with 90 Sx Circulate to surface

Production Casing: 5 1/2" @ 2,028' 15.5#, 8 rd. Cmt with 75 Sx. TOC Calculated @ 1517'. Open Hole 2028 to 2085'.

TUBING: 1" @ 2,071'

Spudded 1/27/52
Drilled open hole section
2028' to 2085' with cable tools.
Shot 2040'-2085' with 85 Qts Nitro.
3-6-52: Tested @ 824 MCFPD.
5-3-52: Installed 99 Jts. 1" Line pipe.

No work recorded in Midland files since completion.

NOT TO SCALE

By: Tom Price 06/06/94 Rick Gaddis 12/22/95