


STATE OF NEW MEXICO
**OIL CONSERVATION
 COMMISSION**
 DISTRICT NO. 3
 Phone 99 P. O. Box 697
 AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
**UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY**

Land Office Albia, N.M.
 Lease No. 77329
 Unit E. L. Bartle

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	



(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Arrington, New Mexico, August 22, 1951

Well No. 2-1 is located 390 ft. from N line and 1165 ft. from E line of sec. 14

1/4 of section 14 (1/4 Sec. and Sec. No.) 1-27-3 (Twp.) 2-10-4 (Range) RPM (Meridian)
Valencia (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6138 ft. (O.S.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On September 9, 1951, at 12:36 P.M., 5 1/2" casing was lowered at 1700 feet with 75 sacks of cement. Rotary rig was moved off location and cable tool rig moved on to drill cement plug and pay. On September 10, 1951, hole was bailed dry and remained dry for two hours. Forty-six feet of solid cement was drilled in bottom of pipe and hole again bailed dry. Hole remained dry for three hours which was considered a satisfactory water shut-off test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil and Gas Company

Address Box 487

Arrington, New Mexico

By _____

Title Inspector

