Form	9-331	
(May	1963	١

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on re-

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R. 424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL	SURVEY	

SHNDRY	NOTICES	ΔND	REPORTS	ON	WELLS
SUINDE	MOTICES	ANU	KEPUK 13	ON	WEFF2

	Mar Cookin				
6.	IF INDIAN, ALLOTTEE	OR	TRIBE	N.	31

Use 'APP.	oposals to arill or to deepen or plug back to a different reservoir. LICATION FOR PERMIT—" for such proposals.)		
OIL GAS WELL OTHE	R	7. UNIT AGREEMENT	NAME
2. NAME OF OPERATOR		8. FARM OR LEASE 1	NAME
3. ADDRESS OF OPERATOR	Company	9. WELL NO.	B
4. LOCATION OF WELL (Report locati See also space 17 below.) At surface	on clearly and in accordance with any State requirements.	10. FIELD AND POOL	
ule ra	1596 PVL	11. SEC., T., R., M., O SURVEY OR AB	
		Land Barry	7751_0000
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PAR	ISH IS. STATE
	6339 Ground Lovel		98000 8400 8

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL

TEST WATER SHIT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

May 12, 1965, Rig up workover. Pulled tubing. Ran Bridge Flug set at 6700. Went in with ensing inspection log. Found holes from 4070-4300. Went in with tubing and squeeze packer. Set packer at 3690. Squeeze with 500 sacks of Class C" ment with Heled 9 mixed .6 of 15 with 25 calcium chloride. Squaeme to 2000f. Set 12 hours. Drilled out cament. Pressure up to 2000 - bald o.k. Drilled out bridge plus, and clean sat. Rem tubing back. But on production. Rig down May 16, 1965.

