UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Well	3	•	
		5.	Lease Number
a		6.	SF-077875 If Indian, All. or
Type of Well		о.	Tribe Name
GAS			TIDE Name
	· -	7.	Unit Agreement Name
Name of Operator			
BURLINGION	1		
OIL & GAS COMPANY		0	Well Name & Number
and the state of Orange of		8.	Rowley #3
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		9	API Well No.
PO BOX 4289, Fallillington, Nin 87499 (303) 320 3700		٠.	30-045-06647
Location of Well, Footage, Sec., T, R, M		10.	Field and Pool
1650'FSL, 800'FEL, Sec.7, T-27-N, R-10-W, NMPM			Fulcher Kutz PC
,		11.	County and State
admire the second secon			San Juan Co, NM
Recompletion X_ Subsequent Report Plugging Back Casing Repair Final Abandonment Altering Casing X_ Other -	_ Non-Ro _ Water	utine : Shut o	Fracturing ff
X Subsequent Report Plugging Back Casing Repair Altering Casing X Other Describe Proposed or Completed Operations 8-26-00 RU. Latch onto 1 %" Rilsan tbg. TOOH w/1 would not fuse. SDON. 8-28-00 Respool 1 %" Rilsan tbg. Fuse additional	Non-Ro Water Conver .653' of	utine : Shut o sion to tbg. A	Fracturing ff o Injection ttempt to fuse tbg, d 1 %" Rilsan Nylon
_X_Subsequent Report Plugging Back Casing Repair Altering Casing X_Other Other S. Describe Proposed or Completed Operations X	Non-Ro Water Conver .653' of	utine : Shut o sion to tbg. A	Fracturing ff o Injection ttempt to fuse tbg, d 1 %" Rilsan Nylon
	Non-Ro Water Conver .653' of . tbg. TI rt. RD. W	tbg. A	Fracturing ff o Injection ttempt to fuse tbg, d 1 %" Rilsan Nylon rned over to product
X_ Subsequent Report Plugging Back Casing Repair Altering Casing X_ Other Other Other	Non-Ro Water Conver .653' of . tbg. TI rt. RD. W	tbg. A	Fracturing ff o Injection ttempt to fuse tbg, d 1 %" Rilsan Nylon rned over to product
	Non-Ro Water Conver .653' of . tbg. TI .t. RD. W	tbg. A	Fracturing ff o Injection ttempt to fuse tbg, d 1 %" Rilsan Nylon rned over to product

· Alexander