

OK

OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

September 4, 1963

British-American Oil Producing Co.
P.O. Drawer 330
Farmington, New Mexico

Attn: Nae R. Stone

E-11-27-11
Re: British-American #6
Fullerton, E-11-27N-13W

Dear Sir:

A packer leakage test was filed for the above well on August 21, 1963. The test consisted of flowing the lower zone for a week or 7 days while the upper zone was shut in. During this 7-day period the upper zone pressure decreased from 1293# to 1252#. The upper zone was evidently not tested for the reason that it was abandoned on January 10, 1962.

The results of the above test seem to indicate the possibility of communication between the 2 zones. Will you please schedule the well for further tests in order that a definite determination may be made. I would suggest that both zones be shut in for a minimum of 7 days and that the upper zone then be flowed to the atmosphere for a 3-hour period and the pressure checked on the lower zone at 15-minute intervals. We will also be glad to consider any other tests which you deem appropriate to prove the isolation of the two zones.

Yours very truly

Emery C. Arnold
Supervisor, District #3

BCA:ks

cc: OCC, Santa Fe, N.M.