

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0.35
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. NM 02294
2. NAME OF OPERATOR Southland Royalty Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1490'N, 1130'E	8. FARM OR LEASE NAME Whitley
14. PERMIT NO.	9. WELL NO. 4
15. ELEVATIONS (Show whether OP, RT, OR, etc.) 6304'GL	10. FIELD AND POOL, OR WILDCAT S. Blanco Pic. Cliffs
	11. SEC., T., R., M., OR ALK. AND SUBST. OR AREA Sec. 8, T-27-N, R- 9-W N. M. P. M.
	12. COUNTY OR PARISH 13. STATE San Juan NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

12-16-87 MOL&RU. TOOH w/packer. TIH. SDFN.
12-17-87 Pump 9# mud, would not circ. Pumped 15 sx. cement. Would not tag. Pumped 30 sx. cement. SDFN.
12-18-87 Tagged plug above perfs @ 420'. Shot 2 squeeze holes @ 1302'. Pumped 40 sx. cement 1340-1460'. Shot 2 squeeze holes @ 150'. Circ. 50 sx to surface. Removed wellhead & set dry hole marker.

Approved as to plugging of the well.
Liability under bond is retained until
surface restoration is completed.

JAN 07 1988

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Drilling Clerk

DATE 12-30-87

(This space for Federal or State office use)

APPROVED BY [Signature]

TITLE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side