

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved.
Budget: Bureau No. 1004-0185
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Meridian Oil Inc.	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	8. FARM OR LEASE NAME Thompson C
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990'N, 990'E	9. WELL NO. 4
14. PERMIT NO	10. FIELD AND POOL, OR WILDCAT W. Kutz Pic. Cliffs
15. ELEVATIONS (Show whether OF, RT, CR, etc.) 5944'GL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10, T-27-N, R-12-W N.M.P.M.
	12. COUNTY OR PARISH 13. STATE San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. HAS THIS WELL PRODUCED OR COMPLETED OPERATIONS? (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

The following is the revised intended procedure to plug & abandon this location during the second quarter 1988:

MOL&RU. Circulate hole w/9.2# mud. Spot 54 sx (63 cu.ft.) Class "B" neat cement to cover open hole and bottom casing to 1386'. WOC. Tag plug. Displace hole w/9.2# mud. Perforate holes @ 501' and 150'. Set retainer at 291' and squeeze 56 sx (65 cu.ft.) Class "B" neat cement under retainer. Displace hole w/9.2# mud. Circulate 52 sx (61 cu.ft.) Class "B" neat cement to surface. Cut off wellhead and set plug & abandonment marker.

RECEIVED
OLY MAIL ROOM

88 FEB -3 PM 2:05

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

I hereby certify that the foregoing is true and correct

Drilling Clerk

SIGNED *[Signature]*

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

NMOCQ