Form 9-881 a (Feb. 1951) 272

5ed. 3 11W

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4. Form Approved.

Land Office Santa Fe

SF 078673

Schlosser-Federal

SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
SUBSEQUENT REPORT OF ABANDONMENT
Supplementary well history Notice of Intention to Shut Off
Communication

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			February 5, 19 64	
Schlosser-Federal			, 17	
Well No. 2 is located.	790 ft. fi	$rom_{-} \begin{Bmatrix} N \\ S \end{Bmatrix} line$	and 790 ft. from Wine of sec. 3	
8M/4 SM/4 Sec. 3	27 X	111	N.M.P.M.	
Dehota Tall Three ignated	(Twp.)	(Range)	(Meridian) Henr Mexico	
CallupCil.lindesignated (Field)		nnty or Subdivision)	(State or Territory)	
The elevation of the	*/above sea	level is 6	210ft.	

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tests indicate communications exists between the Dakota and Gallup formation. It is proposed to move in workover rig, pull tubing, hydrotest and clean tubing, replace damaged tubing, riplace packer if necessary, re-run tubing, test well, and return to production,



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _	Sinclair Oil & Gas Company	
Address	601 Denvar Club Building	
Addices	Denver, Colorado	By -
	Phone 266-2461	By No Eq Brown Title Division Clerk