

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Southland Royalty Company	8. FARM OR LEASE NAME Santa Fe G
3. ADDRESS OF OPERATOR Post Office Box 4289 Farmington, NM 87499	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790'S, 790'W	10. FIELD AND POOL, OR WILDCAT Kutz Gallup
11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 5, T-27-N, R-11-W N.M.P.M.	12. COUNTY OR PARISH San Juan
13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☒

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

On 7-7-88, the Bureau of Land Management approved the plugback recompletion procedure for this well. On 10-17-88, an extension was granted to 11-15-88.

If for some reason the well cannot be recompleted, the following procedure will be used to plug and abandon well.

Spot 25 sx (29 cu.ft.) cmt. from 1850-1640' across Fruitland top inside casing (2nd stage cmt over outside). Displace hole w/9#, 50 vis gel-mud. Perf squeeze holes @ 848' and set cement retainer @ 650' and squeeze 55 sx (64 cu.ft.) cement across Kirtland and Ojo Alamo 848-650'. Displace hole w/9#, 50 vis gel-mud. Perf squeeze holes @ 247' and circ 70 sx (82 cu.ft.) cmt to surface inside casing and annulus. Cut off wellhead and set abandonment marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

Regulatory Affairs

10-26-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side