Form	9-331	a
(Feb	. 1951)	



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Offi	New Hexteo
Lease No	G12200
Unit	Dryden

SUNDRY NOTICES AND REPORTS ON WELLS

		1 1		X
	DRILL		T REPORT OF WATER SHUT-OFF	1
	CHANGE PLANS		T REPORT OF SHOOTING OR ACID	1
NOTICE OF INTENTION TO	TICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	
NOTICE OF INTENTION TO	RE-DRILL OR REPAIR WELL	SUBSEQUEN		
NOTICE OF INTENTION TO	SHOOT OR ACIDIZE	SUBSEQUEN	T REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO	PULL OR ALTER CASING	SUPPLEMEN	TARY WELL HISTORY	
NOTICE OF INTENTION TO	ABANDON WELL	·		
	(INDICATE ABOVE BY CHECK	MARK NATURE OF REPOR	RT, NOTICE, OR OTHER DATA)	.
		*****	Nay 2	, 19. 5 (
/ell No. 3 (#)	is located 990 ft. f	from $\left\{ \begin{matrix} \mathbf{N} \\ \mathbf{S} \end{matrix} \right\}$ line an	d \mathcal{M} ft. from \mathbb{W} 1	ine of sec. 21
SW Section 21	5/3	CW	K.H.F.M.	
(1/4 Sec. and Sec. No.)	.) (Twp.)	(Range)	(Meridian)	
wildcat and Bla	en c o	an Juan	ilev hax	ico
(Field)		•	(State or Te	• 7
	ing points, and	ow sizes, weights, and le d all other important pr	ngths of proposed casings; indica oposed work)	te mudding jobs, cement
Co 4-15-57, Tot Ran 75 joints 7 with 100 sacks followed with 5 Beld 1000g for	ing points, and call Depth 2400'. 7-5,8', J-55, 26.44 regular communt, 1650 sacks Boat community	Of, Casing (2 00 sacks Form	ngths of proposed casings; indicatoposed work) 1369') set at 2399' ix, 50° Flocule and	
Co 4-15-57, Tot Ran 75 joints 7 with 100 sacks followed with 5 Held 1000s for Top of cessest b	ing points, and call Double 2400'. 7-5,8", J-55, 26.46 regular commit, 16 Sacks Best commit 30 minutes. by temperature sur	Consider important processing (2000 sacks Foundate. Yellow at 700'.	oposed work) 2389') set at 2399'	15 Col.
Co 4-15-57, Total Ran 75 joints 7 with 100 sacks followed with 5 Beld 1000 for Top of cement b	ing points, and the last points and last points and last last last comment, 1600 sacks leat comment and minutes. By temperature sur	Consider important processing (2000 sacks Foundate. Yellow at 700'.	2389') set at 2399'	15 Col.
Co 4-15-57, Tot Ran 75 joints 7 with 100 sacks followed with 5 Held 1000s for Top of cessest b	ing points, and call Double 2000'. 7-5,8", J-55, 26.46 regular commit, 16 30 sacks leat commit 30 similes. by temperature sur	Consider important processing (2000 sacks Foundate. Yellow at 700'.	ological Survey before operations	by Gol,
Co 4-15-57, Tot Ran 75 joints 7 with 100 sacks followed with 5 Held 1000s for Top of cessent b	ing points, and call Double 2000'. 7-5,8", J-55, 26.46 regular commit, 16 30 sacks leat commit 30 similes. by temperature sur	Consider important processing (200) sacks Foundate. Yellow at 700'.	ological Survey before operations	45 Col.