Form	9-881 a
(Feb	. 1951)

1			
	,		
		i	
I	l		
	ļ		
	i	;	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Approval expires 12-31-60.
Land Office
Lease No. Johnston
Unit

		· · · · · · · · · · · · · · · · · · ·	11		- X -	
1	ION TO DRILLION TO CHANGE PLANS		1	OF WATER SHUT-OFF		
	ION TO CHANGE PLANS ION TO TEST WATER SHUT-			OF SHOOTING OR ACIDIZIN OF ALTERING CASING		
1	ION TO RE-DRILL OR REPA		11	OF RE-DRILLING OR REPAIR		
NOTICE OF INTENT	ION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT			
	ION TO PULL OR ALTER CA		SUPPLEMENTARY WEL	L HISTORY		
NOTICE OF INTENTI	ION TO ABANDON WELL					
	(INDICATE ABOVE	BY CHECK MARK N	ATURE OF REPORT, NOTICE	, OR OTHER DATA)	·	
			•••	April 11	, 19.57	
Well No. 7	is located 11	80 ft. from	N line and 1840	ft. from E line	of sec	
SW Section		28	(S) unu	N.M.P.K.	01 300.	
(1/4 Sec. and 8 Blanco	ec. No.) (Twp.) (R San Juan		eridian) Mew Maxico		
(Field)			Subdivision)	(State or Territor	у)	
The elevation of	f the derrick floor a	above sea level	l is 5767 ft.			
			S OF WORK			
		DETAIL	OF MOKE			
State names of and a	wasted deaths to objective	de. ekow sisse	malabia and lamatha of an			
State names of and e	xpected depths to objective ing	e sands; show sizes, points, and all othe	weights, and lengths of poer important proposed wo	roposed casings; indicate m rk)	udding jobs, cement	
	ing	points, and all other	weights, and lengths of peer important proposed wo	roposed casings; indicate m rk)	udding jobs, cement	
On 4-4-57 Ran 6 jos	7. Total Depth ints 7-5/8", J-	2245'. 55, 26.40#,	casing (2234)) set at 2244'		
On 4-4-57 Ran 6 jos with .50	7. Total Depth ints 7-5/8", J- sacks regular	2245'. 55, 26.40#,	casing (2234)	rk)		
On 4-4-57 Ran 6 jos with50 and 4% Ge	7. Total Depth ints 7-5/8", J- sacks regular	2245'. 55, 26.40#,	casing (2234)) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Beld 1000	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Beld 1000	7. Total Depth ints 7-5/8", J- sacks regular	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Held 1000	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Held 1000	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Held 1000	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On 4-4-57 Ran 6 joi with .50 and 4% Ge Held 1000	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Poznix, 3) set at 2244'		
On h-h-57 Ran 6 jos with .50 and 4/ Ge Held 1000	7. Total Depth ints 7-5/8", J- sacks regular of al, followed with Of 30 minutes. ment by temper	2245'. 55, 26.40#, commut, \$0 th 50 sacks	casing (2234) sacks Posmix, 3 Heat coment. y at 1545'.	RELIVE APR 22 195	sack	
On 4-4-57 Ran 6 jos with .50 and 4/6 Ge Held 1000 Top of ce	7. Total Depth ints 7-5/8", J- sucks regular of al, followed with Of 30 minutes.	2245'. 55, 26.40g, commit, 50 th 50 sacks	casing (2234) sacks Poznix, Heat commut. y at 1545.	RELEVE APR 22 195 OH. CON. CO	sack	
On h-h-57 Ran 6 jos with .50 and 45 Ge Held 1000 Top of ce	7. Total Depth ints 7-5/8°, J-1 sacks regular of 10 minutes. this plan of work must recommend the same by temperature of 10 minutes.	2245'. 55, 26.40g, commit, 50 th 50 sacks	casing (2234) sacks Poznix, Heat commut. y at 1545.	RELIVE APR 22 195	sack	
Ran 6 jos with 50 and 45 Ge Held 1000 Top of ca	7. Total Depth ints 7-5/8°, J-1 sacks regular of the followed with 30 minutes. The followed with the	2245'. 55, 26.40#, commut, 50 th 50 sacks stare surve; coive approval in wr	casing (2234) sacks Posmix, 3 Heat coment. y at 1545'.	APR 22 195	Sack M. by commenced.	
On 4-4-57 Ran 6 jos with .50 and 4/6 Held 1000 Top of ca	7. Total Depth ints 7-5/8", J- sacks regular of followed with the same of the	2245'. 55, 26.40#, commut, 50 th 50 sacks stare surve; coive approval in wr	casing (2234) sacks Poznix, lest coment. y at 1545'.	RELIVE APR 22 195	M. beformenced.	

U.S. GOVERNMENT PRINTING OFFICE: 1956-O-393560