Form approved. Budget Eureau No. 1004-0135 SUBMIT IN TRIPLICATES Torm 3160-5 November 1983) UNITED STATES Expires August 31, 1985 DEPARTMENT OF THE INTERIOR verse side) 5. LEASE DESIGNATION AND SERIAL NO. Formerly 9-331) BUREAU OF LAND MANAGEMENT SF-079319 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME WELL GAS WELL OTHER S PARM OR LEASE NAME 2. NAME OF OPERATOR Schwerdtfeger A Tenneco Oil Company WBLL NO. 3. ADDRESS OF OPERATOR P. O. Box 3249 Englewood, CO 80155 LOCATION OF WELL (Report location clearly and in accordance with any State resultemental D at surface 10. FIELD AND POOL, OR WILDCAT Basin Dakota 11. EBC., T., R., M., OR BLK. AND SURVEY OR AREA 1190' FNL, 790' FWL JUN 2 7 1985 BUREAU OF LAND MANAGEMENT Sec. 31, <u>T28N R8W</u> 12. COUNTY OR PARISH | 13. STATE 15. BLEVATIONS (Show whether of, at, GR, etc.) 14. PERMIT NO. 5876' GR San Juan NM Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16 NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TERT WATER SHUT-OFF ALTERING CABING MULTIPLE COMPLETE FRACTURE TREATMENT FRACTURE TREAT BROOTING OR ACIDIZING ABANDON\* SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL (Nork: Report results of multiple completion on We. Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) \* Tenneco requests permission to Re-Frac the reference well according to the attached detailed procedure. APPROVED that the foregoing is trite and correct 18. I bereby certify TITLE Senior Regulatory Analyst 6/23/85 SIGNED (This space for Federal or State office use) TITLE APPROVED BY PLYABEA MANAGER CONDITIONS OF APPROVAL, IF ANY: FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

255'

0069/3
LEASE Schwerdtfegar "A"
WELL NO. 2-X

## CASING:

10 3/4 "OD, 32.75 LB, H-40 CSG. W/ 200 SX

TOC @ surf . HOLE SIZE 15" DATE 12/14/66

REMARKS

7 5/8 "OD, 24.0 LB, H-40 CSG. W/ 200 SX

TOC @ surf . HOLE SIZE 5/8 DATE 12/17/66

REMARKS

4 1/2 "OD, 10.5/11.6LB J-55 CSG. W/ 185/450 SX

TOC @ 4326' . HOLE SIZE 6 3/4" DATE 12/23/66

## TUBING:

2 3/8 "OD, 4.7 LB, J-55 GRADE 8 RD, EUE CPLG LANDED @ 6550 . SN, PACKER, ETC.SN 1 Jt.

REMARKS\_\_DV at 4723'

#### off bottom

# **DETAILED PROCEDURE:**

- 1. Blow down Dakota
- MIRU workover rig. Kill w/1% KCL wtr. NDWH. NUBOP's
- 3. RIH with tubing and CO to PBTD if necessary.
- 4. RIH with pkr on tubing to 6400'. Set pkr at 6400'.
- 5. PT BS to 3000 PSI. If BS doesn't PT, call Denver. POOH with tubing and pkr.
- 6. Foam frac Dakota with 70% quality foam in 1% KCL water with 20# Gel/1000 gal water and 20-40 sand as follows:

### 20 BPM

<u>Volume, Gal</u>	Prop Con. PPG	Cum Prop., LB
7000	0	0
5000	1.0	5000
6000	2.0	17000
<b>700</b> 0	3.0	38000

Job Totals: 25000 gal. 70% Quality foam and 38000# 20-40 sand. Maximum surface treating pressure: 3000 psig

- S.I. well for 3 hours. Flow to pit overnight
- through a 1/2" tapped bull plug.

  8. RIH with 2 3/8" tubing, seating nipple, and pump out plug. CO to PBTD with foam.
- Land tubing at + 6550'
- 10. Kick well around with No
- 11. FTCU
- 12. Return well to production.

PERFS 4715'. SQZD

2361

PERFS 6510' - 88'

PERFS 6606'-12'
CMT, RTNR, @ 6625'

PERFS 6644'-6706'

0069