

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other _____
2. NAME OF OPERATOR
SOUTHWEST PRODUCTION COMPANY
3. ADDRESS OF OPERATOR
P. O. Box 400, Aztec, New Mexico 87410
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: NE/4 NE/4 Sec. 6-27N-11W
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: 330/N 330/E
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- | | |
|----------------------|-------------------------------------|
| TEST WATER SHUT-OFF | ☐ |
| FRACTURE TREAT | ☐ |
| SHOOT OR ACIDIZE | ☐ |
| REPAIR WELL | ☐ |
| PULL OR ALTER CASING | ☐ |
| MULTIPLE COMPLETE | ☐ |
| CHANGE ZONES | ☐ |
| ABANDON* | ☒ |
| (other) | |

SUBSEQUENT REPORT

- | |
|--|
| |
| |
| |
| |
| |
| |
| |

JAN 4 1983
U. S. GEOLOGICAL SURVEY
F. W. WASHINGTON

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

- | | |
|--|-------------------|
| 5. LEASE
SF - 078895 | |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 7. UNIT AGREEMENT NAME | |
| 8. FARM OR LEASE NAME
Graham Federal | |
| 9. WELL NO.
1 | |
| 10. FIELD OR WILDCAT NAME
Kutz Gallup | |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 6 T27N R11W | |
| 12. COUNTY OR PARISH
San Juan | 13. STATE
N.M. |
| 14. API NO. | |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD)
6017' GL | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Approval to plug & abandon GRAHAM FEDERAL #1.

Well records indicate the following information:

Surface csg. 10 3/4" set @ 302' w/200 sxs. Drilled 7 7/8" hole to 5915'.

Production csg. 4 1/2" set @ 5910' w/220 sxs. DV tool @ 1998'; staged 125 sxs.

It is proposed to P & A this well in the following manner:

30' surface plug leaving 4 1/2" csg. in hole, cut off below ground level, as per NAPI.

350' - 250' Cement plug inside & outside 4 1/2" csg. Perf. csg. @ 350'
w/4 holes.

-OVER-

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *F. L. Crum Jr.* TITLE _____ DATE 1/3/83

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE _____

*See Instructions on Reverse Side

NMOCC

RECEIVED
JAN 6 1933
OIL CON. DIV.
DIST. 3

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-149

		Perforate @:			
Ojo	650'	Cement plug interval	600' - 750'	Inside & outside 4 1/2" csg.	750' w/4 holes
Pictured Cliffs	1787'	"	"	"	DV tool @1998' w/125 sxs
		"	1740' - 1840'	"	
Cliffhouse	2725'	"	"	"	3430' w/4 holes
		"	3330' - 3430'	"	
Pt. Lookout	4264'	"	"	"	4314' w/4 holes
		"	4214' - 4314'	"	
Gallup	5395'	"	"	"	5732' - 5748'
		"	5720' - 5820'	"	5797' - 5818'

Also need plug from 2700-2800 inside & outside casing