

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease <input checked="" type="checkbox"/> State <input type="checkbox"/> FED. <input type="checkbox"/> Other
5. State Oil & Gas Lease No. NA-0359211

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Beta Development Co.	8. Farm or Lease Name Creda Federal
3. Address of Operator 125 Petr. Club Plaza, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER K , 1850 FEET FROM THE South LINE AND 1830 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 27N RANGE 11W NMPM.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6143' G.L.	12. County San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to repair well as follows:

Rig up workover rig, circulate out mud, sand and shale to T.D. Circulate until hole is clean, POH. Run Baker Model "D" production packer on wire line. Set packer just below Greenhorn section w/bump-out plug to keep any water or Kem-Pac material from getting below packer. GIH w/tubing, Model "D" locator and tail pipe. Spot Kem-Pac above Model "D", set tail pipe down on bump-out plug, run tail pipe through Model "D" and land locator seals in packer. Flange up well head, swab well in, re-acidize if necessary.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original signed by:

D. E. BAXTER

TITLE

Superintendent

DATE

Feb. 19, 1969

SIGNED

APPROVED BY

[Signature]

TITLE

SUPERVISOR DIST. #3

DATE

FEB 20 1969

CONDITIONS OF APPROVAL, IF ANY: