				1	
NO. OF COPIES RECEIVED	6				
DISTRIBUTION	NEW MEN	400 ON CONSERVATION OF		-	
SANTA FE	. 1 1	CICO OIL CONSERVATION CO REQUEST FOR ALLOWABL		Form C-104 Supersedes O	ld C-104 and C-11
FILE	7	AND	C	Effective 1-1-	
U.S.G.S.	AUTHORIZATION	N TO TRANSPORT OIL AN	D NATURAL (GAS	
LAND OFFICE	, a monitario	it is indicated and old all	D INTOKAL .	FII	
TRANSPORTER OIL GAS	7			OFI.H	VED/
OPERATOR	2			\ Urnr.	
PRORATION OFFICE				1 404 1 0	1968
Operator				MOAT	
Ri Paso Natura	L Gas Company			OIL CON	COM.
Box 990, Farmir Reason(s) for filing (Check pro	ngton, New Mexico - 87	7401 Other (Ple	ease explain)	Dis	
New Well	Change in Transporter	r of:			
Recompletion	Oil	Dry Gas			
Change in Ownership	Casinghead Gas	Condensate			
If change of ownership give and address of previous own					
DESCRIPTION OF WELL	AND LEASE Well No. Pool Name,	Including Formation	Kind of Leas	se	Lease No.
Rissell Location		Blanco Pictured Clif	State, Feder	al or Fee	IM 13860
Unit Letter;	1840 Feet From The Sou	th Line and 150	YO Feet From	The East	
Line of Section 25	Township 28N	Range 81 , NA	ирм,	San Juan	County
DESIGNATION OF TRAN	SPORTER OF OIL AND NAT	TURAL GAS			
Name of Authorized Transporte		Sidence (Cine addes	111		1-1
i rame or maniorated transporte	t of Oil Oil or Coursements	Address (Give dudie	ess to which appro	oved copy of this form is	to be sent;
1		Mar-			
El Paso Natura		Box 990		oved copy of this form is on, New Hexico oved copy of this form is	
Rl Paso Natural	Cas Company	Box 990 Gas X Address (Give addre	Farmingt	on, New Mexico	- 87401 to be sent)
El Paso Natura	r of Casinghead Gas or Dry Casinghead Gas Twp.	Box 990 Gas Address (Give addre Box 990 Rge. Is gas actually conv	Farmingt state of the state of		- 87401 to be sent)
Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming	r of Casinghead Gas or Dry Casinghead Gas Twp.	Box 990 Gas Address (Give addre Box 990 Rge. Is gas actually conn), Farmingt ess to which appro), Farmingt lected?	on, New Mexico oved copy of this form is on, New Mexico	- 87401 to be sent)
Name of Authorized Transporte El Paso Natura If well produces oil or liquids, give location of tanks.	Gas Company or of Casinghead Gas or Dry Company Unit Sec. Twp. J 25 28 gled with that from any other lea	Box 990 Gas Address (Give addre Box 990 Rge. Is gas actually conn EW se or pool, give commingling o	Farmingt Farmingt Farmingt We dected? We rder number:	con, New Mexico oved copy of this form is con, New Mexico hen	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Con	Gas Company or of Casinghead Gas or Dry Company Unit Sec. Twp. J 25 28 gled with that from any other lea	Box 990 Gas X Address (Give addre Box 990 Rge. Is gas actually conn EW se or pool, give commingling o Gas Well New Well Workov	Farmingt Farmingt Farmingt We dected? We rder number:	con, New Mexico oved copy of this form is con, New Mexico hen	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded	L Gas Company or of Casinghead Gas or Dry or Dr	Box 990 Gas X Address (Give addre Box 990 Rge. Is gas actually conn EW se or pool, give commingling o Gas Well New Well Workov	Farmingt Farmingt Farmingt We dected? We rder number:	con, New Hexico oved copy of this form is con, New Hexico hen Plug Back Same Re	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68	L Gas Company or of Casinghead Gas or Dry Ca	Box 990 Gas X Address (Give address 1990) Rige. Is gas actually connot be a see or pool, give commingling of Gas Well New Well Workow X X X d. Total Depth 2870	Farmingt Farmingt Farmingt We dected? We rder number:	plug Back Same Re	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL	L Gas Company or of Casinghead Gas or Dry Ca	Box 990 Gas X Address (Give addre Box 990 Rge. Is gas actually conr See or pool, give commingling of Gas Well New Well Workov X X d. Total Depth 2870 tion TopXXI/Gas Pay	Farmingt Farmingt Farmingt We dected? We rder number:	P.B.T.D. 2860' Tubing Depth	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations	I Gas Company I Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Producing Format etc.; Name of Producing Format	Box 99% Gas X Address (Give addre Box 99% Rge. Is gas actually conn EW se or pool, give commingling of Gas Well New Well Workov X X d. Total Depth 2870 tion TopXXI/Gas Pay	Farmingt Farmingt Farmingt We dected? We rder number:	P.B.T.D. 2860' Tubing Depth Depth Casing Shoe	- 87401 to be sent) - 87401
R1 Paso Natural Name of Authorized Transporte R1 Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Production of Producing Format Pictured Clif	Box 99% Gas X Address (Give addre Box 99% Rge. Is gas actually conn EW se or pool, give commingling of Gas Well New Well Workov X X d. Total Depth 2870 tion TopXXI/Gas Pay	Parmingt iss to which appro Parmingt ected? When rder number: er Deepen	P.B.T.D. 2860' Tubing Depth	- 87401 to be sent) - 87401
El Paso Natural 'Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL. Perforations 2750 - '74'	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Proc 11-12-68 Pictured Clif	Box 990 Gas X Address (Give address) Box 990 Rige. Is gas actually connounced to the second process of the	Parmingt ss to which appro Parmingt ected? When the company of th	P.B.T.D. 2860' Tubing Depth Depth Casing Shoe	- 87401 to be sent) - 87401
The Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE	crof Casinghead Gas or Dry Casinghead Gas or	Box 990 Gas X Address (Give address) Box 990 Rige. Is gas actually connounced to the second process of the	Parmingt ss to which appro Parmingt ected? When the company of th	Plug Back Same Report Tubing Depth Casing Shoe 2870	- 87401 to be sent) - 87401
The Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218 GL. Perforations 2750 - '74' HOLE SIZE 12 1/4"	TUBING, CASING & TUBING, CASING & TUBING	Box 990 Gas X Address (Give address) Rige. Is gas actually connounced to the second	Parmingt ss to which appro Parmingt ected? When the company of th	P.B.T.D. 2860 Tubing Depth Tubingles Depth Casing Shoe 2870	- 87401 to be sent) - 87401
The Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE	crof Casinghead Gas or Dry Casinghead Gas or	Box 990 Gas X Address (Give address) Box 990 Rige. Is gas actually connounced to the property of the proper	Parmingt ss to which appro Parmingt ected? When the company of th	Plug Back Same Report Tubing Depth Casing Shoe 2870' SACKS CE 95 Sks.	- 87401 to be sent) - 87401 es/v. Diff. Res/v
The Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218 GL. Perforations 2750 - '74' HOLE SIZE 12 1/4"	TUBING, CASING & TUBING, CASING & TUBING	Box 990 Gas X Address (Give address) Box 990 Rige. Is gas actually connounced to the property of the proper	Parmingt ss to which appro Parmingt ected? When the company of th	Plug Back Same Report Tubing Depth Casing Shoe 2870' SACKS CE 95 Sks.	- 87401 to be sent) - 87401
El Paso Natura Name of Authorized Transporte El Paso Natura If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE 12 1/4" 6 3/4"	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Production Format Pictured Clif TUBING, CASING & TUBING 8 5/8" 2 7/8" EST FOR ALLOWABLE (Te	Box 990 Gas X Address (Give address) Rege. Is gas actually connocent to the second s	Parmingt Secret With the secre	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks.	** 87401 to be sent) ** 87401 ** 87401 ** Sompleti
The Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Compate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218 GL. Perforations 2750 - '74' HOLE SIZE 12 1/4"	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Production Format Pictured Clif TUBING, CASING & TUBING 8 5/8" 2 7/8" EST FOR ALLOWABLE (Te	Box 990 Gas X Address (Give address) Rge. Is gas actually connormal to the second se	Parmingt Secretary We reder number: Per Deepen CORD H SET	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	** 87401 to be sent) ** 87401 ** 87401 ** Sompleti
This production is comming COMPLETION DATA Designate Type of Compared Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218° GL Perforations 2750 - '74° HOLE SIZE 12 1/4° 6 3/4° TEST DATA AND REQUI	cr of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 Galed with that from any other lea Impletion — (X) Date Compl. Ready to Product of Producing Format Pictured Clif TUBING, CASING & TUBING 8 5/8" 2 7/8" EST FOR ALLOWABLE (Teab	Box 990 Gas X Address (Give address) Rege. Is gas actually connocent to the second s	Parmingt Secretary We reder number: Per Deepen CORD H SET	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	** 87401 to be sent) ** 87401 es/v. Diff. Res/v
TEST DATA AND REQUICED. To Matura Test Paso Natura To Matura T	cr of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 Galed with that from any other lea Impletion — (X) Date Compl. Ready to Product of Producing Format Pictured Clif TUBING, CASING & TUBING 8 5/8" 2 7/8" EST FOR ALLOWABLE (Teab	Box 990 Gas X Address (Give address) Rge. Is gas actually connormal to the second se	Parmingt Secretary We reder number: Per Deepen CORD H SET	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	** 87401 to be sent) ** 87401 es/v. Diff. Res/v
El Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Condition Date Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE 12 1/4" 6 3/4" TEST DATA AND REQUIPMENT OIL WELL Date First New Oil Run To Tale	TUBING, CASING & TUBING & TUBING, CASING & TUBING & TUB	Box 990 Gas X Address (Give address) Box 990 Rige. Is gas actually connounced to the second process of the	Parmingt Secretary We reder number: Per Deepen CORD H SET	Plug Back Same Report Same Report Casing Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	** 87401 ** 87401 ** 87401 ** 87401 ** STATE OF THE S
El Paso Natura Name of Authorized Transporte El Paso Natura If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Cord Date Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218 GL.) Perforations 2750 - '74' HOLE SIZE 12 1/4" 6 3/4" TEST DATA AND REQUIONI. WELL Date First New Oil Run To To Length of Test Actual Prod. During Test	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Producting Format Pictured Clif TUBING, CASING & TUBING 8 5/8 ¹¹ 2 7/8 ¹¹ EST FOR ALLOWABLE (Teabours) Tubing Pressure	Box 990 Gas X Address (Give address) Box 990 Rge. Is gas actually connounced by the second	Parmingt Secretary We reder number: Per Deepen CORD H SET	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	** 87401 ** 87401 ** 87401 ** 87401 ** STATE OF THE S
El Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Condition Date Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE 12 1/4" 6 3/4" TEST DATA AND REQUITATION OIL WELL Date First New Oil Run To Total Length of Test	r of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Producting Format Pictured Clif TUBING, CASING & TUBING 8 5/8 ¹¹ 2 7/8 ¹¹ EST FOR ALLOWABLE (Teabours) Tubing Pressure	Box 990 Gas X Address (Give address) Box 990 Rge. Is gas actually connounced by the second	rder number: Deepen Deepen CORD H SET	P.B.T.D. 2860' Tubing Depth Tubingles Depth Casing Shoe 2870' SACKS CE 95 Sks. 170 Sks.	- 87401 to be sent) - 87401 es'v. Diff. Res'v. S Completi MENT
El Paso Natural Name of Authorized Transporte El Paso Natural If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Condition Date Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - 74' HOLE SIZE 12 1/4" 6 3/4" TEST DATA AND REQUITOR WELL Date First New Oil Run To Total Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D	L Gas Company or of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Product of Producing Format Pictured Clif TUBING, CA CASING & TUBING 8 5/8 ¹¹ 2 7/8 ¹¹ EST FOR ALLOWABLE (Teaborned Clif) Tubing Pressure Oil-Bbls.	Box 990 Gas X Address (Give address) Rige. Is gas actually contained by the second process of the second pro	rder number: Deepen Deepen CORD H SET	Plug Back Same Report Same Rep	- 87401 to be sent) - 87401 estv. Diff. Restv. S Completi MENT
R1 Paso Natura Name of Authorized Transporte E1 Paso Natura If well produces oil or liquids, give location of tanks. If this production is comming COMPLETION DATA Designate Type of Condate Spudded 9-2-68 Elevations (DF, RKB, RT, GR, 6218' GL Perforations 2750 - '74' HOLE SIZE 12 1/4" 6 3/4" TEST DATA AND REQUITOR WELL Date First New Oil Run To To Length of Test Actual Prod. During Test	L Gas Company or of Casinghead Gas or Dry of Gas Company Unit Sec. Twp. J 25 28 gled with that from any other lea mpletion — (X) Date Compl. Ready to Product of Producing Format Pictured Clif TUBING, C. CASING & TUBING 8 5/8# 2 7/8# EST FOR ALLOWABLE (Teable) inks Date of Test Tubing Pressure Oil-Bbls. Length of Test 3 Hours 1.) Tubing Pressure (Shut-i	Box 990 Address (Give address) Box 990 Rige. Is gas actually connounced by the second process of the second	rder number: Deepen Deepen CORD H SET	Plug Back Same Report Same Rep	- 87401 to be sent) - 87401 estv. Diff. Restv. S Completi MENT

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

Original signed by

		Matthew
(Signa	ture)	

Petroleum Engineer

(Title)

November 15, 1968

(Date)

NUV19 1968 APPROVED_

By Original Signed by Emery C. Arnold

TITLE .

SUPERVISOR DIST. #3

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II, III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply completed wells.